



CIVIL ENGINEERING ASSOCIATES, INC.

10 Mansfield View Lane
South Burlington, VT 05403

Phone: 802-864-2323
E-Mail: dmarshall@cea-vt.com

October 11, 2023

Mr. Ryan Morrison, Zoning Administrator
Town of Stowe
P.O. Box 730
Stowe, VT 05672

**Re: Development Application – Turf Care Center Redevelopment
Stowe Country Club, LLC
Project 7200 – 744 Cape Cod Road at 400 Cape Cod Road**

Dear Mr. Morrison:

In accordance with guidance provided by the Development Review Board at the October 3, 2023 Site Plan and Conditions Use hearing, the applicant had revised and supplemented the application materials.

Generally, the following revisions were made to the application package.

1. Added the roof eave lines to the proposed buildings to provide a more accurate representation of the building setback compliance.
2. Building A was relocated to the south to provide full compliance with the 60' rear yard setback requirement.
3. The plans have been cleaned up to remove ambiguities and to present the proposed conditions in a clearer manner. The plan numbers were made sequential and the most up to date building plans have been substituted.
4. Added stockade fencing along the south side of the site to further screen the building from Cape Cod Road.
5. Added limitations on area light illumination during nighttime hours.
6. We have created renderings of the landscape as seen from various view points along Cape Cod Road (Attachments 3 and 4)
7. We have added detail to the building floor plans to better indicate floor sloping, floor curb locations as part of the spill containment efforts for each building.
8. Provided a written narrative describing the spill containment measures to be employed in the project (Attachment 6).

9. Added P1 and P2 drawings to depict the self-contained nature of the floor and drainage systems.

10. Updated the aesthetics of the buildings by:

- Faux window punchouts have been added to the south side of Building C (along Cape Cod Road) to create additional interest and to break-up the length of the building.
- Utilizing and exterior comprised of “Charcoal” insulated panels and LP SmartSide “Midnight Shadow” vertical Board and Batten siding. The Board and Batten (See Attachment 6) will be installed on:

Building A: south, east and west sides (everything but the back)

Building C: south, east and west sides (everything but the front)


The LP Smartside Features include advanced durability through the use of engineered wood technology offering superior protection against the elements.

LP Smartside Board & Batten Color – Midnight Shadow (see Attach. 5 for aesthetic)




Garage Doors – color selected - Gray

Color options



Eight (8) windows on the back of building “C” – black (these are dummy windows)



As Viewed From The Exterior

Please find outlined below the revisions that have been integrated with short narratives describing the intent of each.

Civil Plan Sheets

C1.0 – Existing Conditions Plan (1"=30')– The plan has been revised to show the current property line based upon the recent administrative approval of a lot line adjustment between this parcel and the golf course parcel to the north.

C1.10 – Existing Conditions Plan (1'=20') – This plan was revised similarly as Sheet C1.0.

C1.20 – Demolition Plan – This is a new sheet to provide a concise representation of the demolition components.

C2.00 – Proposed Conditions Plan

- Removed references to work on the adjacent property to the west .
- Removed the old property line and depicted the current property lines
- Added the roof overhang on the buildings and moved Building A to comply with the 60' rear yard setback requirement.
- Added a Proposed parking summary table at the bottom right of the plan.
- Added a stockade fence along the south side of Building C.
- The front yard setback from Building C was revised to 39 feet to reflect the inclusion of the eave on the south side of the building.

L1.00 – Landscaping Plan

- Removed old property line
- Added stockade fence along the south side of Building C.
- Consolidated notes from Sheet L1.01 on this sheet and eliminated L1.01.
- Added likeness image of stockade fence.

C2.20 – Proposed Drainage Plan

- Updated the proposed grading to be consistent with the berm grading shown on Sheet L1.0.
- Add a note about retaining the existing gravel along the west property line.
- Removed the old property line and depicted the current property lines
- Added a stockade fence along the south side of Building C.

C2.30 – Proposed Utility Plan

- Moved the meter pad and disconnect switch 10' away from the building.
- Removed the old property line and depicted the current property lines
- Added a stockade fence along the south side of Building C.

C2.40 – Site Lighting Plan

- Formalized the Lumen Count and Density calculations.
- Added narrative regarding operation of the lights after hours.

C3.00 – EPSC P Plan

- Updated the proposed grading to be consistent with the berm grading shown on Sheet L1.0.
- Removed the old property line and depicted the current property lines
- Added a stockade fence along the south side of Building C.

C4.00 – Site Details

- Added note to Dumpster Enclosure Detail regarding inclusion of a roof and screening on all four sides.

A1 – Building A Turf Care Maintenance Facility

- Added code compliance references and building features tables.
- Added Board & Batten siding on south side

A3 – Building C Environmental Management Center

- Added code compliance references and building features tables.
- Added dummy windows on south elevation
- Added Board & Batten siding on south, east and west sides
- Updated overhead doors
- Added hatching to the solid wall portions of the building.
- Removed CarbTrol treatment system for clarity

A1.1, A2.2, A3.3, E3 – Eliminated for Clarity

E2 – Building C Environmental Management Center Electrical Plan

- Added hatching to the solid wall portions of the building.

M2 – Building C Environmental Management Center Electrical Plan

- Added hatching to the solid wall portions of the building.

Mr. Ryan Morrison

Page 5 of 5

October 11, 2023

P1 – Building C Environmental Management Center Drainage Plan – Plan Added

P2 – Building C Environmental Management Center Plumbing for Carbtrol System – Plan Added

This completes our summary of the revised and supplemental information materials, if you should have any questions or require any additional information, please feel free to contact me at dmarshall@cea-vt.com or 802-864-2323 x310.


Respectfully,

A handwritten signature in blue ink, appearing to read 'D. Marshall', with a long horizontal flourish extending to the right.

David S. Marshall, P.E.

Principal Engineer

- Enclosures:
- 1 - Revised Civil Plan Set - Last Rev 10.10.23
 - 2 - Revised Architectural Plan Set – Last Rev. 10.10.23
 - 3 - Rendering Central NE View from Cape Cod Road
 - 4 - Rendering of NW View from Cape Cod Road
 - 5 - Board & Batten Siding Example
 - 6 - Combined Spill Control Info Package



LOCATION MAP
1" = 2000'

LEGEND

	APPROXIMATE PROPERTY LINE
	APPROXIMATE SETBACK LINE
	EXISTING CONTOUR
	EXISTING CURB
	EXISTING FENCE
	EXISTING GRAVEL
	EXISTING PAVEMENT
	EXISTING GUARD RAIL
	EXISTING ELECTRIC
	EXISTING FORCEMAIN
	EXISTING GAS
	EXISTING STORM
	EXISTING GRAVITY SEWER
	EXISTING TELEPHONE
	EXISTING WATER
	EXISTING SWALE
	STREAM
	WETLANDS
	WETLANDS BUFFER
	EXISTING SEWER MANHOLE
	EXISTING STORM MANHOLE
	EXISTING CATCH BASIN
	EXISTING YARD DRAIN
	EXISTING WELL
	EXISTING HYDRANT
	EXISTING SHUT OFF
	EXISTING UTILITY POLE
	EXISTING LIGHT POLE
	EXISTING GUY WIRE/POLE
	EXISTING SIGN
	EXISTING DECIDUOUS TREE
	EXISTING CONIFEROUS TREE
	EDGE OF BRUSH/WOODS
	IRON ROD/PIPE FOUND
	CONCRETE MONUMENT FOUND
	TEST PIT
	PERCOLATION TEST
	PROJECT BENCHMARK

NOTES

- UTILITIES SHOWN DO NOT PURPORT TO CONSTITUTE OR REPRESENT ALL UTILITIES LOCATED UPON OR ADJACENT TO THE SURVEYED PREMISES. EXISTING UTILITY LOCATIONS ARE APPROXIMATE ONLY. THE CONTRACTOR SHALL FIELD VERIFY ALL UTILITY CONFLICTS. ALL DISCREPANCIES SHALL BE REPORTED TO THE ENGINEER. THE CONTRACTOR SHALL CONTACT DIG SAFE (888-344-7233) PRIOR TO ANY CONSTRUCTION.
- THIS PLAN IS NOT A BOUNDARY SURVEY AND IS NOT INTENDED TO BE USED AS ONE.
- PROPERTY LINE INFORMATION ON THE NORTH AND WEST SIDES IS APPROXIMATE AND THE GOLF COURSE PERIMETER BOUNDARY SURVEY PREPARED BY LITTLE RIVER SURVEY COMPANY DATED 9/1994. THE SOUTH AND EAST LINES ARE BASED ON INTERPRETATION OF LINE EXTENSIONS FROM THE LITTLE RIVER SURVEY AND PARCEL MAPPING.
- SITE INFORMATION IS BASED ON A FIELD SURVEY PERFORMED BY CIVIL ENGINEERING ASSOCIATES, INC. MAY 2023. CIVIL ENGINEERING ASSOCIATES, INC. SURVEY ORIENTATION IS "GRID NORTH", VERMONT COORDINATE SYSTEM OF 1983 (HORIZONTAL) AND NAVD88 (VERTICAL) ESTABLISHED FROM GPS OBSERVATIONS ON SITE.
- PROJECT BENCHMARK IS LAKE CHAMPLAIN ESTABLISHED FROM THE UNITED STATES GEOLOGICAL SURVEY GAUGING STATION 04294500 LOCATED IN BURLINGTON, VERMONT. (DATUM NGVD 29)
- CONTOUR INFORMATION IS BASED UPON TOPOGRAPHICAL SURVEY PERFORMED BY CIVIL ENGINEERING ASSOCIATES, INC. MAY 2023. HORIZONTAL AND VERTICAL DATUM BASED ON VCS NAD 83 AND NAVD 88.



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23

REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO.

23158

MADE BY

SAL

REVIEWED BY

DSM

SCALE

1"=30'

**EXISTING
CONDITIONS
PLAN**

C1.00

GRAPHIC SCALE




(IN FEET)
1 inch = 30 ft.

P:\AutoCAD\Projects\2023\23158 - SPR TCCU - CADD Files\23158.dwg 10/10/2023 1:00:22 PM DWG to PDF.pc3

LEGEND

- APPROXIMATE PROPERTY LINE
- - - APPROXIMATE SETBACK LINE
- - - 100' EXISTING CONTOUR
- ==== EXISTING CURB
- x - EXISTING FENCE
- - - EXISTING GRAVEL
- ==== EXISTING PAVEMENT
- o - EXISTING GUARD RAIL
- E - EXISTING ELECTRIC
- FM - EXISTING FORCEMAIN
- G - EXISTING GAS
- ST - EXISTING STORM
- S - EXISTING GRAVITY SEWER
- T - EXISTING TELEPHONE
- W - EXISTING WATER
- ← EXISTING SWALE
- ==== STREAM
- WETLANDS
- WETLANDS BUFFER
- ⊙ EXISTING SEWER MANHOLE
- ⊙ EXISTING STORM MANHOLE
- ⊙ EXISTING CATCH BASIN
- ⊙ EXISTING YARD DRAIN
- ⊙ EXISTING WELL
- ⊙ EXISTING HYDRANT
- ⊙ EXISTING SHUT OFF
- ⊙ EXISTING UTILITY POLE
- ⊙ EXISTING LIGHT POLE
- ⊙ EXISTING GUY WIRE/POLE
- ⊙ EXISTING SIGN
- ⊙ EXISTING DECIDUOUS TREE
- ⊙ EXISTING CONIFEROUS TREE
- ⊙ EDGE OF BRUSH/WOODS
- ⊙ IRON ROD/PIPE FOUND
- ⊙ CONCRETE MONUMENT FOUND
- ⊙ TEST PIT
- ⊙ PERCOLATION TEST
- ⊙ PROJECT BENCHMARK



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23

REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO.

23158

MADE BY

SAL

REVIEWED BY

DSM

SCALE

1"=20'

**EXISTING
CONDITIONS
PLAN**

C1.10

P:\AutoCAD\Projects\2023\23158 - SPR TCC1 - CADD Files\23158.dwg 23158 - Site.dwg 10/10/2023 1:00:31 PM DWG TO PDF.pc3

LEGEND

- APPROXIMATE PROPERTY LINE
- APPROXIMATE SETBACK LINE
- - - - - 100' --- EXISTING CONTOUR
- ==== EXISTING CURB
- x - - - EXISTING FENCE
- - - - - EXISTING GRAVEL
- ==== EXISTING PAVEMENT
- - - - - EXISTING GUARD RAIL
- E - - - EXISTING ELECTRIC
- FM - - - EXISTING FORCEMAIN
- G - - - EXISTING GAS
- ST - - - EXISTING STORM
- S - - - EXISTING GRAVITY SEWER
- T - - - EXISTING TELEPHONE
- W - - - EXISTING WATER
- EXISTING SWALE
- ==== STREAM
- WETLANDS
- WETLANDS BUFFER
- ⊙ EXISTING SEWER MANHOLE
- ⊙ EXISTING STORM MANHOLE
- ⊙ EXISTING CATCH BASIN
- ⊙ EXISTING YARD DRAIN
- ⊙ EXISTING WELL
- ⊙ EXISTING HYDRANT
- ⊙ EXISTING SHUT OFF
- ⊙ EXISTING UTILITY POLE
- ⊙ EXISTING LIGHT POLE
- ⊙ EXISTING GUY WIRE/POLE
- ⊙ EXISTING SIGN
- ⊙ EXISTING DECIDUOUS TREE
- ⊙ EXISTING CONIFEROUS TREE
- ⊙ EDGE OF BRUSH/WOODS
- ⊙ IRON ROD/PIPE FOUND
- ⊙ CONCRETE MONUMENT FOUND
- ⊙ TEST PIT
- ⊙ PERCOLATION TEST
- ⊙ PROJECT BENCHMARK



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cca-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

8.8.23

REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO.

23158

MADE BY

SAL

REVIEWED BY

DSM

SCALE

1"=20'

**DEMOLITION
PLAN**

GRAPHIC SCALE



(IN FEET)
1 inch = 20 ft.


C1.20

LEGEND

	PROPOSED PROPERTY LINE
	PROPOSED SETBACK LINE
	PROPOSED CONTOUR
	PROPOSED CURB
	PROPOSED FENCE
	PROPOSED GRAVEL
	PROPOSED PAVEMENT
	PROPOSED GUARD RAIL
	PROPOSED ELECTRIC
	PROPOSED FORCE MAIN
	PROPOSED GAS
	PROPOSED STORM
	PROPOSED GRAVITY SEWER
	PROPOSED TELEPHONE
	PROPOSED WATER
	PROPOSED SWALE
	PROPOSED SEWER MANHOLE
	PROPOSED STORM MANHOLE
	PROPOSED CATCH BASIN
	PROPOSED YARD DRAIN
	PROPOSED WELL
	PROPOSED HYDRANT
	PROPOSED SHUT OFF
	PROPOSED UTILITY POLE
	PROPOSED LIGHT POLE
	PROPOSED GUY WIRE/POLE
	PROPOSED SIGN
	PROPOSED EDGE OF BRUSH/WOODS
	REBAR SET
	CONCRETE MONUMENT SET


GENERAL NOTES

- UTILITIES SHOWN DO NOT PURPORT TO CONSTITUTE OR REPRESENT ALL UTILITIES LOCATED UPON OR ADJACENT TO THE SURVEYED PREMISES. EXISTING UTILITY LOCATIONS ARE APPROXIMATE ONLY. THE CONTRACTOR SHALL FIELD VERIFY ALL UTILITY CONFLICTS. ALL DISCREPANCIES SHALL BE REPORTED TO THE ENGINEER. THE CONTRACTOR SHALL CONTACT DIG SAFE (888-344-7233) PRIOR TO ANY CONSTRUCTION. IN ADDITION, THE CONTRACTOR SHALL HIRE A PRIVATE UTILITY LOCATING FIRM TO LOCATE OWNER OWNED UNDERGROUND UTILITIES PRIOR TO START OF ANY EXCAVATION.
- ALL EXISTING UTILITIES NOT INCORPORATED INTO THE FINAL DESIGN SHALL BE REMOVED OR ABANDONED AS INDICATED ON THE PLANS OR DIRECTED BY THE ENGINEER.
- THE CONTRACTOR SHALL MAINTAIN AS-BUILT PLANS (WITH TIES) FOR ALL UNDERGROUND UTILITIES. THOSE PLANS SHALL BE SUBMITTED TO THE OWNER AT THE COMPLETION OF THE PROJECT.
- THE CONTRACTOR SHALL REPAIR/RESTORE ALL DISTURBED AREAS (ON OR OFF THE SITE) AS A DIRECT OR INDIRECT RESULT OF THE CONSTRUCTION.
- ALL GRASSED AREAS SHALL BE MAINTAINED UNTIL FULL VEGETATION IS ESTABLISHED.
- MAINTAIN ALL TREES OUTSIDE OF CONSTRUCTION LIMITS.
- THE CONTRACTOR SHALL BE RESPONSIBLE FOR ALL WORK NECESSARY FOR COMPLETE AND OPERABLE FACILITIES AND UTILITIES.
- THE CONTRACTOR SHALL SUBMIT SHOP DRAWINGS FOR ALL ITEMS AND MATERIALS INCORPORATED INTO THE SITE WORK. WORK SHALL NOT BEGIN ON ANY ITEM UNTIL SHOP DRAWING APPROVAL IS GRANTED.
- IN ADDITION TO THE REQUIREMENTS SET IN THESE PLANS AND SPECIFICATIONS, THE CONTRACTOR SHALL COMPLETE THE WORK IN ACCORDANCE WITH ALL PERMIT CONDITIONS AND ANY LOCAL PUBLIC WORKS STANDARDS.
- THE TOLERANCE FOR FINISH GRADES FOR ALL PAVEMENT, WALKWAYS AND LAWN AREAS SHALL BE 0.1 FEET. UNLESS NOTED OTHERWISE, ALL EXISTING MANHOLE COVERS, VALVES, CURB STOPS AND OTHER ITEMS TO REMAIN SHALL BE ADJUSTED TO THE NEW FINISH GRADE.
- ANY DEWATERING NECESSARY FOR THE COMPLETION OF THE SITework SHALL BE CONSIDERED AS PART OF THE CONTRACT AND SHALL BE THE CONTRACTOR'S RESPONSIBILITY.
- THE CONTRACTOR SHALL COORDINATE ALL WORK WITHIN TOWN ROAD R.O.W. WITH TOWN AUTHORITIES.
- THE CONTRACTOR SHALL INSTALL THE ELECTRICAL, CABLE AND TELEPHONE SERVICES IN ACCORDANCE WITH THE UTILITY COMPANIES REQUIREMENTS.
- EXISTING PAVEMENT AND TREE STUMPS TO BE REMOVED SHALL BE DISPOSED OF AT AN APPROVED OFF-SITE LOCATION. ALL PAVEMENT CUTS SHALL BE MADE WITH A PAVEMENT SAW.
- IF THERE ARE ANY CONFLICTS OR INCONSISTENCIES WITH THE PLANS OR SPECIFICATIONS, THE CONTRACTOR SHALL CONTACT THE ENGINEER FOR VERIFICATION BEFORE WORK CONTINUES ON THE ITEM IN QUESTION.
- PROPERTY LINE INFORMATION IS APPROXIMATE AND BASED ON EXISTING TAX MAP INFORMATION. THIS PLAN IS NOT A BOUNDARY SURVEY AND IS NOT INTENDED TO BE USED AS ONE.
- IF THE BUILDING IS TO BE SPRINKLERED, BACKFLOW PREVENTION SHALL BE PROVIDED IN ACCORDANCE WITH AWWA M14. THE SITE CONTRACTOR SHALL CONSTRUCT THE WATER LINE TO TWO FEET ABOVE THE FINISHED FLOOR. SEE MECHANICAL PLANS FOR RISER DETAIL.
- THE CONTRACTOR IS RESPONSIBLE FOR OBTAINING TESTING AND INSPECTION SERVICES INDICATED IN THE CONTRACT DOCUMENTS, TYPICAL FOR CONCRETE AND SOIL TESTING.
- THE CONTRACTOR IS RESPONSIBLE FOR ALL LAYOUT AND FIELD ENGINEERING REQUIRED FOR COMPLETION OF THE PROJECT. CIVIL ENGINEERING ASSOCIATES WILL PROVIDE AN AUTOCAD FILE WHERE APPLICABLE.
- THE OWNER SHALL BE RESPONSIBLE FOR THE INSTALLATION OF ANY AND ALL SAFETY FENCES OR RAILS ABOVE EXISTING AND PROPOSED WALLS. THE OWNER SHALL VERIFY LOCAL, STATE AND INSURANCE REQUIREMENT GUIDELINES FOR THE INSTALLATION AND VERIFY ANY AND ALL PERMITTING REQUIREMENTS.



PARKING SPACE SUMMARY
THE ZONING REGULATION DO NOT PROVIDE SPECIFIC REQUIREMENTS OR TURF CARE CENTERS

DESIGN DEMAND	SPACES PROVIDED
12 EMPLOYEES X 1 SPACE / EMPLOYEE	12
3 VISITOR / VENDER SPACES	3
TOTAL SPACES	15



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23


REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO. 23158
MADE BY SAL
REVIEWED BY DSM
SCALE 1"=30'

**PROPOSED
CONDITIONS
PLAN**

C2.00




PLANT LIST

Key	Quan	Scientific Name	Common Name	Size
CoR	6	Cornus racemosa	Gray Dogwood	3 gal.
CoS	2	Cornus sericea	Redtwigged Dogwood	3 gal.
PhG	9	Physocarpus opulifolius 'Ginger Wine'	Ginger Wine Ninebark	3 gal.
PhS	6	Physocarpus opulifolius 'Summer Wine'	Summer Wine Ninebark	3 gal.
PIG	4	Picea glauca	White Spruce	5-6 ft.
PINS	2	Picea glauca 'North Star'	North Star White Spruce	6 gal.
Plo	2	Picea omorika	Serbian Spruce	5-6 ft.
Qua	1	Quercus alba	White Oak	3" Cal.
ThN	4	Thuja occidentalis 'Nigra'	Dark Green Arborvitae	4-5 ft.
ThS	4	Thuja occidentalis 'Emerald Green'	Emerald Green Arborvitae	5-6 ft.
ThT	3	Thuja occidentalis 'Techney'	Techney Arborvitae	4-5 ft.
Tm	8	Taxus x media 'Hicksii'	Hicks Yew	5 gal.

SITE ENGINEER:

 CIVIL ENGINEERING ASSOCIATES, INC.
 10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
 802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com
 COPYRIGHT © 2022 - ALL RIGHTS RESERVED

SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
 CAPE COD ROAD
 STOWE, VT 05672



CoR - Gray Dogwood



CoS - Redtwigged Dogwood



PhG - Ginger Wine Ninebark



PhS - Summer Wine Ninebark



PIG - White Spruce



Plo - Serbian Spruce



Qua - White Oak



ThN - Dark Green Arborvitae



ThS - Emerald Green Arborvitae



Tm - Hicks Yew




PINS - North Star White Spruce



ThT - Techney Arborvitae



Stockade Fence



CROSS SECTION A-A SCALE: 1"=10'

ISSUE
 PRICING SET
 RELEASE DATE
 6.2.23
 REVISIONS
 10/10/23 PER TOWN COMMENTS

PROJECT NO. 23158
 MADE BY SAL
 REVIEWED BY DSM
 SCALE 1"=20'

LANDSCAPE PLAN

L1.00

P:\AutoCAD\Projects\2023\23158 - Spruce Peak Real Estate\23158 - Spruce Peak Real Estate.dwg 10/10/2023 3:57:51 PM DWG To PDF.pc3



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
 10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
 802-864-2323 FAX: 802-864-2271 web: www.cca-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
 STOWE COUNTRY CLUB
 TURF CARE CENTER
 CAPE COD ROAD
 STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23

REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO.

23158

MADE BY

SAL

REVIEWED BY


DSM

SCALE

1"=20'

**PROPOSED
 DRAINAGE PLAN**

GRAPHIC SCALE



(IN FEET)
 1 inch = 20 ft.

C2.20

P:\AutoCAD\Projects\2023\23158 - SPR TCCU - CADD Files\23158.dwg 1:06:46 PM, DWG to PDF.pc3

Stowe Country Club, Turf Care Center
 Test Pits
 May 18, 2023

D. Marshall

TP 1 (South East)
 0'-3" Brown, loose, sandy loam, granular, single grain, 1-5%, round
 3'-24" Brown, loose, coarse sand, granular, single grain, 6-15%, round
 24'-44" Pinkish gray, medium compact, coarse sand, granular, single grain, 15-35%, round
 44'-68" Brown, medium compact, coarse sand, granular, single grain, 15-35%, round
 68'-74" Light gray, loose, coarse sand, granular, single grain, 1-5%, round

Depth to SHGWT - None	Depth of Heavy Roots 24"	Depth of Fine Roots 37"
Depth to Seeps- None	Depth to Ledge-None	Ground Slope 1%

TP 2
 0'-4" Brown, loose, fine sandy loam, blocky, weak, 1-5%, round
 4'-10" Strong brown, loose, loamy sand, granular, single grain, 6-15%, round
 10'-26" Brown, loose, coarse sand, granular, single grain, 16-35%, round
 26'-43" Pinkish gray, medium compact, coarse sand, granular, single grain, 16-35%, round
 43'-51" Strong brown, loose, coarse sand, granular, single grain, 16-35%, round
 51'-75" Light gray, loose, coarse sand, granular, single grain, 6-15%, round

Depth to SHGWT - None	Depth of Heavy Roots 32"	Depth of Fine Roots 48"
Depth to Seeps- None	Depth to Ledge-None	Ground Slope 1%

TP 3
 0'-3" Light brown, loose, fine sandy loam, blocky, weak, 1-5%, round
 3'-22" Light brown, loose, loamy sand, granular, single grain, 6-15%, round
 22'-32" Brown, loose, coarse sand, granular, single grain, 16-35%, round
 32'-48" Dark brown, medium compact, coarse sand, granular, single grain, 16-35%, round
 48'-57" Brown, medium compact, coarse sand, granular, single grain, 16-35%, round
 57'-67" Strong brown, loose, coarse sand, granular, single grain, 16-35%, round
 67'-73" Light gray, loose, coarse sand, granular, single grain, 6-15%, round

Depth to SHGWT - None	Depth of Heavy Roots 19"	Depth of Fine Roots 49"
Depth to Seeps- None	Depth to Ledge-None	Ground Slope 1%



SITE ENGINEER:


 CIVIL ENGINEERING ASSOCIATES, INC.
 10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
 802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com
 COPYRIGHT © 2022 - ALL RIGHTS RESERVED

**SPRUCE PEAK REALTY
 STOWE COUNTRY CLUB
 TURF CARE CENTER
 CAPE COD ROAD
 STOWE, VT 05672**

ISSUE
 PRICING SET
 RELEASE DATE
 6.2.23
 REVISIONS
 10/10/23 PER TOWN COMMENTS

PROJECT NO. 23158
 MADE BY SAL
 REVIEWED BY DSM
 SCALE 1"=20'

**PROPOSED
 UTILITY PLAN**



C2.30

P:\AutoCAD\Projects\2023\23158 - SPR TCCU - CADD File\23158.dwg 10/10/2023 1:07:28 PM, DWG to PDF.pc3

SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED



**SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23

REVISIONS

10/10/23 PER TOWN COMMENTS

LIGHTING CALCULATION SUMMARY

LUMINAIRE SCHEDULE						
TYP	SYMBOL	DESCRIPTION	LUMENS	MOUNTING HEIGHT	QTY	TOTAL LUMENS
W1	□	LSI INDUSTRIES INC. (SLICE MEDIUM) (1) SLM-LED-9L-SIL-2-UNV-DIM-30-70CRI-ALSCS04-EXT-BRZ	9,411	WALL - 11'	5	47,055
W2	□	LSI INDUSTRIES INC. (SLICE MEDIUM) (1) SLM-LED-9L-SIL-3-UNV-DIM-30-70CRI-ALSCS04-EXT-BRZ	9,548	WALL - 11'	1	9,548
W3	□	LSI INDUSTRIES INC. (SLICE MEDIUM) (1) SLM-LED-9L-SIL-5W-UNV-DIM-30-70CRI-ALSCS04-EXT-BRZ	9,261	WALL - 11'	1	9,261
P1	○	LSI INDUSTRIES INC. (SLICE MEDIUM) (1) SLM-LED-12L-SIL-2-UNV-DIM-30-70CRI-ALSCS04-EXT-BRZ	12,533	POLE - 14'	2	25,066
P2	○	LSI INDUSTRIES INC. (SLICE MEDIUM) (1) SLM-LED-12L-SIL-3-UNV-DIM-30-70CRI-ALSCS04-EXT-BRZ	12,714	POLE - 14'	1	12,714

LIGHTING LEVEL LEGEND

- 10.0 FOOTCANDLES
- 5.0 FOOTCANDLES
- 1.0 FOOTCANDLES
- 0.5 FOOTCANDLES
- 0.1 FOOTCANDLES

GENERAL PHOTOMETRIC SCHEDULE

AVERAGE FOOT-CANDLES	0.70
MAXIMUM FOOT-CANDLES	11.8


Site Lighting Programming

The area lights will be set on a timer in which the lights will be turned off one-hour after astronomical sunset. Lights will be enabled to be turned on no sooner than one-hour before astronomical sunrise.

During nighttime hours all of the exterior lights will be programmed to turned on from a signal from a motion detector. The lights will stay on for 15 minutes before resorting to the off mode.

Motion sensors will be set so that they are not triggered by pass-by traffic on Cape Cod Road.

GRAPHIC SCALE



103,644 TOTAL LUMENS
51,461 DEVELOPMENT AREA
103,644 LUMENS / SF DEVELOPMENT AREA

PROJECT NO. 23158
MADE BY SAL
REVIEWED BY DSM
SCALE 1"=30'

SITE LIGHTING PLAN

C2.40

P:\AutoCAD\Projects\2023\23158 - SPR TCC1 - CAODD File: 23158.dwg 23158 - Site.dwg 10/10/2023 4:05:34 PM, DWG to PDF.pc3



SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
 10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
 802-864-2323 FAX: 802-864-2271 web: www.cea-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED



**SPRUCE PEAK REALTY
 STOWE COUNTRY CLUB
 TURF CARE CENTER
 CAPE COD ROAD
 STOWE, VT 05672**

ISSUE

PRICING SET

RELEASE DATE

6.2.23

REVISIONS

10/10/23 PER TOWN COMMENTS

PROJECT NO.

23158

MADE BY

SAL

REVIEWED BY


DSM

SCALE

1"=30'

EPSC PLAN










GRAPHIC SCALE




(IN FEET)
 1 inch = 30 ft.

C3.00

P:\AutoCAD\Projects\2023\23158 - SPR TCC\1-CADD Files\23158.dwg 10/10/2023 1:09:14 PM DWG to PDF.pc3






- NOTES:
1. COMPACTION OF BACKFILL AND BEDDING SHALL BE A MINIMUM OF 90% (95% UNDER ROADWAY SURFACES) OF MAXIMUM DRY DENSITY DETERMINED IN THE STANDARD PROCTOR TEST (ASTM D698).
 2. BEDDING MATERIAL SHALL NOT BE PLACED ON FROZEN SUBGRADE.
 3. APPROVED BACKFILL SHALL NOT CONTAIN ANY STONES MORE THAN 12" IN LARGEST DIMENSION (6" IN ROADWAYS, 1 1/2" MAXIMUM DIAMETER WITHIN 24" OF THE OUTSIDE OF THE PIPE), OR CONTAIN ANY FROZEN, WET, OR ORGANIC MATERIAL.
 4. TRENCHES SHALL BE COMPLETELY DEWATERED PRIOR TO PLACING OF PIPE BEDDING MATERIAL AND KEPT DEWATERED DURING INSTALLATION OF PIPE AND BACKFILL.
 5. IN TRENCHES WITH UNSTABLE MATERIALS OR HIGH WATER TABLE, TRENCH BOTTOM SHALL FIRST BE STABILIZED BY PLACEMENT OF FILTER FABRIC THEN CRUSHED STONE (3/4" MAXIMUM).
 6. THE SIDES OF TRENCHES 4' OR MORE IN DEPTH ENTERED BY PERSONNEL SHALL BE SHEETED OR SLOPED TO THE ANGLE OF REPOSE AS DEFINED BY O.S.H.A. STANDARDS.
 7. BEDDING MATERIAL SHALL CONSIST OF CRUSHED STONE, OR SAND WITH A MAXIMUM SIZE OF 3/4". SUBMIT A SAMPLE TO THE ENGINEER FOR APPROVAL.
 8. CONTRACTOR TO INSTALL TRACER WIRE ALONG ALL SECTIONS OF NEW WATER LINE. TERMINATE TRACER WIRE AT ALL VALVE BOXES AND HYDRANTS. COORDINATE INSTALLATION WITH TOWN AND ENGINEER.

TYPICAL WATER TRENCH DETAIL
N.T.S.

1000 Gallon (Single Compartment) Step Seamless Step / Pump Tank (1000Step)




SPECIFICATIONS:

- Concrete Minimum Strength 5000psi @ 28 days
- Steel Reinforcement Grade 60
- Poly IV Booted Connections
- Top Seam Construction
- Weights Subject to Variation


CAMP
PRECAST CONCRETE PRODUCTS
78 PRECAST ROAD, MILTON, VT 05468 405.893.3001
TOLL FREE 1.888.299.2401 FAX 802.893.1542
CAMP Precast Concrete Products www.CAMPRECAST.com
Revision Date: 3/1/2006 Section: 5

GENERAL NOTES:

- ALL TANKS TO BE WATER-PROOF w/ BOOTED CONNECTIONS



1,000 GALLON HOLDING TANK
N.T.S.




- NOTES:
1. COMPACTION OF BACKFILL AND BEDDING SHALL BE A MINIMUM OF 90% (95% UNDER ROADWAY SURFACES) OF MAXIMUM DRY DENSITY DETERMINED IN THE STANDARD PROCTOR TEST (ASTM D698).
 2. BEDDING MATERIAL SHALL NOT BE PLACED ON FROZEN SUBGRADE.
 3. APPROVED BACKFILL SHALL NOT CONTAIN ANY STONES MORE THAN 12" IN LARGEST DIMENSION (6" IN ROADWAYS, 1 1/2" MAXIMUM DIAMETER WITHIN 24" OF THE OUTSIDE OF THE PIPE), OR CONTAIN ANY FROZEN, WET, OR ORGANIC MATERIAL.
 4. TRENCHES SHALL BE COMPLETELY DEWATERED PRIOR TO PLACING OF PIPE BEDDING MATERIAL AND KEPT DEWATERED DURING INSTALLATION OF PIPE AND BACKFILL.
 5. IN TRENCHES WITH UNSTABLE MATERIALS OR HIGH WATER TABLE, TRENCH BOTTOM SHALL FIRST BE STABILIZED BY PLACEMENT OF FILTER FABRIC THEN CRUSHED STONE (3/4" MAXIMUM).
 6. THE SIDES OF TRENCHES 4' OR MORE IN DEPTH ENTERED BY PERSONNEL SHALL BE SHEETED OR SLOPED TO THE ANGLE OF REPOSE AS DEFINED BY O.S.H.A. STANDARDS.
 7. BEDDING MATERIAL FOR WASTEWATER LINES SHALL CONSIST OF CRUSHED STONE, GRAVEL, OR SAND WITH A MAXIMUM SIZE OF 3/4". SUBMIT A SAMPLE TO THE ENGINEER FOR APPROVAL.
 8. ALL JOINTS TO BE INSPECTED BY OWNER/ENGINEER/TOWN PRIOR TO BACKFILL.

TYPICAL SEWER TRENCH DETAIL
N.T.S.

The tanks shall be tested by the following procedure and in conformance with the State of Vermont - Environmental Protection Rules:

1. **Exfiltration Leakage Test:** All pipes and other openings into the tank shall be suitably plugged and the plugs braced to prevent blowout. The tank shall then be filled with water to the top of the riser section. A period of time may be permitted, if the Contractor so wishes, to allow for absorption. At the end of this period, the tank shall be refilled to the top of the riser, if necessary, and the measuring time of at least four hours begun. At the end of the test period, the tank shall be refilled to the top of the riser, measuring the volume of water added. This amount shall be converted to gallons per vertical foot depth for 24 hours. The leakage for each tank shall not exceed four gallon/vertical foot/day. If leakage exceeds the allowable rate, repairs shall be made as approved by the Engineer and the tank retested. If the Contractor elects to backfill prior to testing, the testing shall be at his own risk, and it shall be incumbent upon the Contractor to determine the reason for any failure of the test. No adjustment in the leakage allowance will be made for unknown causes such as leaking plugs, absorption, etc. It will be assumed that all loss of water during the test is a result of leaks through the joints or through the concrete. Furthermore, the Contractor shall take any steps necessary to assure the Engineer that the water table is below the bottom of the tank throughout the test.
- OR
2. **Vacuum test** in accordance with ASTM C1227-03, Standard Specification for Precast Concrete Septic Tanks, except as noted below:
 - seal the empty tank and apply a vacuum to 5 inches (100mm) of mercury. The tank is approved if 90% of vacuum is held for 5 minutes.

TANK TESTING NOTES



*CLEANOUT TO BE INSTALLED AT INTERVALS OF NOT MORE THAN 100 FEET, AND UPSTREAM OF BEND(S) IN BUILDING SEWER(S) WHEN CHANGE IN DIRECTION EXCEEDS 45° (USE LONG SWEEP FITTINGS WHEN EXCEEDING 45°)

TYPICAL CLEANOUT DETAIL
N.T.S.

SITE ENGINEER:



CIVIL ENGINEERING ASSOCIATES, INC.
10 MANSFIELD VIEW LANE, SOUTH BURLINGTON, VT 05403
802-864-2323 FAX: 802-864-2271 web: www.cca-vt.com

COPYRIGHT © 2022 - ALL RIGHTS RESERVED

SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672

ISSUE

PRICING SET

RELEASE DATE




6.2.23

REVISIONS

PROJECT NO. 23158
MADE BY SAL
REVIEWED BY DSM
SCALE AS SHOWN

WATER AND SEWER DETAILS

C4.10




Horizontal Distance (Feet)

	Leach field	Septic Tank	Sewer
Drilled Well Serving 1 Home - Up Slope of Disposal Field	100 (Min.)	50	50
Drilled Well Serving 1 Home - Down Slope of Disposal Field	200 (Min.)	50	50
Shallow Well or Spring, Up Slope of Disposal Field	150 (Min.)	75	75
Shallow Well or Spring, Down Slope of Disposal Field	500 (Min.)	75	75
Lakes, Ponds and Impoundment	50	25	25
Rivers, Streams	50	25	10
Drainage Swales, Roadway Ditches	25	25	10
Municipal Water Main	50	50	10
Service Water Lines	25	25	10
Roadways, Driveways, Parking Lots	10	5	5'
Top of embankment or slope > 30%	25	10	-
Property Line	10 (25 Downslope) ²	10	10
Trees	10	10	10
Replacement Area	10	-	-
Foundation, Footing Drains, Perimeter of a Building	35 (75 Downslope) ³	10	-

- Isolation distances to well locations may vary due to site conditions - contact Engineer for verification with the Vermont Water Supply Rule Regulations.
- For mound disposal systems, the limit of mound fill must be 25 feet from any downhill property line and 10 feet from side or uphill property lines.
- If a curtain or foundation drain is downslope of the leach field, the leach field cannot be closer than 75 feet to the drain. If the drain is upslope of the leach field, it shall be 35' if possible and 20' minimum.
- Sewers under roads, driveways or parking lots may require protective conduits or sleeves.

MINIMUM ISOLATION DISTANCES
(CONTACT ENGINEER FOR ANY CLARIFICATIONS OR CONFLICTS)

SWR-100 REVISED 08/23/2022



DISPOSAL FIELDS & FORCE MAINS

PART 1 - GENERAL

1.01 Summary

A. Section includes:

- Wastewater Disposal Field
- Force Main Materials

1.02 References

A. All work shall be done in accordance with the State of Vermont Environmental Protection Rules effective April 12, 2019.

PART 2 - PRODUCTS

2.01 General

A. Disposal Fields: Schedule 40 PVC pipe meeting the requirements of the latest revision of ASTM Specification D-1785. Fittings used in the disposal fields shall be compatible with distribution lines material.

B. Force Mains: PVC pipe shall conform in all respects to the latest revisions of ASTM Specifications D-2241. All pipe fittings shall be SDR 26 (or SCH 40) clearly marked as follows:

- Manufacturer's Name and Trademark
- Nominal Pipe Size (as shown on plans)
- Material Designation

Joints shall be push-on type using elastomeric gaskets factory installed conforming to ASTM Specification D-3212.

C. Crushed stone shall be clean, durable and no smaller than 3/4 or larger than 1 1/2 inches in diameter, and no larger than 1-1/2 inch in diameter. No more than 1.5 percent of fines passing the #200 sieve as determined using the AASHTO test method T 11-85 and a hardness value of three or greater on the Moh's Scale of Hardness.

PART 3 - EXECUTION

3.01 Disposal Field Installation Procedure

A. The wastewater system shall be inspected during critical stages of construction by a qualified consultant. This shall include at a minimum the staking of the disposal field, the trenches after the initial 24 inches of stone and distribution piping is placed, and a final inspection of the entire system. The Contractor will be responsible for contacting the Engineer to set up the inspection schedule.

B. Construction of the system shall not take place when the soil moisture is high in the system area. If the soil at 6 inches below grade can be rolled into the shape of a wire, the soil moisture content is too high for construction to begin.

C. When the trench has been excavated, the sides and bottom shall be raked to scarify any smeared soil surfaces. Construction equipment not needed to construct the system should be kept off the area to be utilized for the absorption trench system to prevent undesirable compaction of the soils.

D. At least 24 inches of washed stone shall be placed in the bottom of the trench.

E. The pressure distribution pipe should be laid level on top of the stone and flushing valves installed at the ends of the pipe. Upon completion of the distribution piping, the qualified consultant shall test the system with clean water. The test shall show that a minimum pressure of three feet of head is present at the ends of the pipe and that the difference in discharge rate between the two orifices with the greatest difference in discharge rates is not greater than 15 percent. After connecting the distribution pipe to the force main, the distribution pipe shall be covered with at least two inches of clean stone aggregate. The stone aggregate shall be covered completely with filter fabric.

F. The distribution pipe shall be covered with at least 2 inches of clean stone aggregate. The stone aggregate shall be covered completely with filter fabric.

G. The filter fabric shall be covered with a minimum of 6 inches of soil but not more than 12 inches, with the upper 4 to 6 inches of soil being loam and the remainder of the fill being of a fine sandy loam to medium sand texture. A vegetated cover free of large brush and trees shall be maintained over the system.

H. The area surrounding the disposal field shall be graded to provide diversion of surface run-off waters if required.

3.02 Testing Report

A. Testing of pressure distribution shall be done in the Engineer's presence. Pressure shall be measured to insure a minimum of 1 psi.

B. The distribution line shall then be carefully placed on the bedding with no slope, orifice shields snapped into place, and covered with at least 2" of crushed stone.

C. All work shall be done in accordance with the State of Vermont Environmental Protection Rules.

D. Force Main

1. General: All force mains shall pass the hydrostatic pressure test and leakage test described herein. Prior to testing, all anchors and braces shall be installed. All concrete thrust blocks and restraints shall be in place and cured at least seven days. All buried pipe shall be backfilled. Suitable test plugs shall be installed and air release valves shall be installed at the high points.

2. Hydrostatic Test: The following procedure shall be used:

- All air release valves shall be opened and the pipe shall be filled with water at a rate not to exceed the venting capacity of the air release valves.
- The water pressure shall be raised to 150 percent of the designed operating pressure or 60 psi minimum at the highest point.
- Failure to hold the designated pressure within 5 psi of the specified test pressure for the two hour period constitutes a failure of the section tested.

3. Leakage Test: The following procedure shall be used:

- Leakage shall be defined as the quantity of water that must be supplied into the pipe being tested to maintain pressure within 5 psi of the specified test pressure.
- No pipe installation shall be accepted if the leakage is greater than that determined by the following formula:

$$L = \frac{ND(P)0.5}{7,400}$$

$$L = \frac{SD(P)0.5}{133,100}$$

Which ever is less

S = Length of Pipe Testing
L = Allowable Leakage in Gal/Hr
D = Nominal Diameter of Pipe ("")
P = Average Test Pressure (psi)
N = Number of Joints in the Pipeline Tested

All testing shall be conducted in accordance with AWWA C600-87 or latest revision.










E. Prior to use of the system, the qualified consultant shall submit a written report to the Owner stating that the system has been installed according to the approved plans and permit. The report shall specifically address the inspection of the site preparations and include numerical results of the orifice discharge rate comparison.



SPRUCE PEAK REALTY
STOWE COUNTRY CLUB
TURF CARE CENTER
CAPE COD ROAD
STOWE, VT 05672

ISSUE
PRICING SET
RELEASE DATE
6.2.23
REVISIONS

PROJECT NO. 23158
MADE BY SAL
REVIEWED BY DSM
SCALE AS SHOWN
WASTEWATER DETAILS

C4.20








DOOR TYPES
 DOOR A - 3'-0"x6'-8", FIBERGLASS INSULATED, LEVER HARDWARE, 1/2 GLASS
 DOOR B - 3'-0" X 6'-8" METAL NON-INSULATED LEVER HARDWARE, NO GLASS
 DOOR C - 3'-0"x6'-8", METAL NON-INSULATED, LEVER HARDWARE, 1/2 GLASS
 DOOR D - 6'-0"x6'-8", METAL NON-INSULATED, LEVER HARDWARE, 1/2 GLASS
 DOOR E - 12'-0"x12'-0", METAL INSULATED OVERHEAD DOOR (R-10), MANUAL OPERATION OR POWERED
 DOOR G - 12'-0" X 10'-0" METAL INSULATED OVERHEAD DOOR (R-17), MANUAL OPERATION

ENERGY CODE REVIEW BELOW GRADE WALLS
 CONCRETE FOUNDATION, CONDITIONED (R-15 CONTINUOUS)
 CONCRETE FOUNDATION, SEMI-CONDITIONED (R-7.5 CONTINUOUS)

FLOOR TYPES
 SLAB-ON-GRADE, SEMI-CONDITIONED, INSULATED 24 IN FROM EXTERIOR (R-10)
 SLAB-ON-GRADE, CONDITIONED AT RADIANT HEAT, INSULATE ENTIRE AREA UNDER RADIANT (R-20)

WALL TYPES
 EXTERIOR, CONDITIONED (R-13+R-17 CONTINUOUS -or- R-22, 1 CONTINUOUS)
 EXTERIOR, SEMI-CONDITIONED (R-15.8 CONTINUOUS)

ROOF TYPES
 CONDITIONED (R-40 CONTINUOUS ABOVE DECK -or- R-25 + R-11 + R-11 LINER SYSTEM)
 SEMI-CONDITIONED (R-25 CONTINUOUS ABOVE DECK -or- R-19 + R-11 LINER SYSTEM -or- R-25 + R-8 LINER SYSTEM)



CODE REVIEW
 NEW CONSTRUCTION

APPLICABLE CODES
 2015 VERMONT FIRE & BUILDING SAFETY CODE (VT AMENDMENTS TO APPLICABLE CODES)
 2015 IBC
 2015 NFPA 101 LIFE SAFETY CODE
 2015 NFPA 1
 2017 VERMONT ELECTRICAL RULES
 2018 VERMONT PLUMBING RULES
 2012 VERMONT ACCESS RULES (VT AMENDMENTS TO ADA)
 2010 ADA AMERICANS WITH DISABILITY ACT ACCESSIBILITY STANDARDS
 2020 VERMONT ENERGY CODE

CONSTRUCTION TYPE
 2B

OCCUPANCY CLASSIFICATION
 BUSINESS - IBC CHAPTER 3, BUSINESS GROUP B / NFPA 101 CHAPTER 38, NEW BUSINESS OCCUPANCIES
 STORAGE - IBC CHAPTER 3, MODERATE HAZARD STORAGE 5-1 / NFPA 101 CHAPTER 42, STORAGE OCCUPANCIES, LOW & ORDINARY HAZARD

OCCUPANCY LOAD
 BUSINESS - NFPA 10, TABLE 7.3.1.2 - 100SF/PERSON - 1900 SF/100 = 19
 MAX PROBABLE POPULATION - NFPA 101, 42.1.7

HEIGHT & AREA
 ALLOWABLE AREA (NON-SPRINKLERED) - 17,500 SF - IBC TABLE 506.2
 PROPOSED AREA (NON-SPRINKLERED) - 10,585 SF
 ALLOWABLE BUILDING HEIGHT IN FEET ABOVE GRADE PLANE (NON-SPRINKLERED) - 55 FT - IBC TABLE 504.3
 PROPOSED BUILDING HEIGHT (NON-SPRINKLERED) - 16'-6"
 ALLOWABLE # OF STORIES (NON-SPRINKLERED) - 2 - IBC TABLE 504.4
 PROPOSED # OF STORIES (NON-SPRINKLERED) - 1

FIRE RESISTANCE RATING REQUIREMENTS FOR BUILDING ELEMENTS
 (PRIMARY STRUCTURAL FRAME, EXTERIOR/INTERIOR BEARING WALLS, EXTERIOR/INTERIOR NON-BEARING WALLS, FLOOR, ROOF)
 ALLOWABLE RATING IN HOURS - 0 - IBC TABLE 601
 PROPOSED RATING IN HOURS - 0

FIRE SEPARATION OF OCCUPANCIES
 NFPA TABLE 6-1, 14.4.1
 2 HR REQUIRED BETWEEN BUSINESS & STORAGE LOW/ORDINARY HAZARD


NUMBER OF EXITS
 ALLOWABLE # OF EXITS - 2 - NFPA 101, 38.2.4 & 42.2.4.1, W/ TABLE 42.2.5
 PROPOSED # OF EXITS BUSINESS - 2
 PROPOSED # OF EXITS STORAGE - 2

#	Revisions	By
1	15-16-2023	RM
2	15-19-2023	RM
3	15-30-2023	RM
4	16-6-2023	RM
5	16-8-2023	RM





**BUILDING "A" TURF CARE
 MAINTENANCE FACILITY
 FLOOR PLAN & ELEVATIONS**

**STOWE COUNTRY CLUB
 TURF CARE CENTER**
 Stowe, Vermont

930 East Barre Rd.
 P.O. Box 449
 East Barre, Vermont 05649
 P. 802-479-1078
 F. 802-479-1070



FLOOR PLAN & ELEVATIONS
 Date: 4-28-2023
 Scale: 1/8" = 1'-0"
 Drawn By: RM




REVISION DATE: 10/10/2023
 PRINT DATE: 10/10/2023

#	Revisions	By
1	6-8-2023	RM
2		
3		
4		
5		

STRUCTURE "B" BULK
 MATERIAL STORAGE
 FLOOR PLAN & ELEVATIONS

STOWE COUNTRY CLUB
 TURF CARE CENTER
 Stowe, Vermont

930 East Barre Rd.
 P.O. Box 449
 East Barre, Vermont 05649
 P. 802-479-1078
 F. 802-479-1070




FLOOR PLAN &
 ELEVATIONS
 Date: 4-28-2023
 Scale: 3/16" = 1'-0"
 Drawn By: RM


STATE OF VERMONT AGENCY OF AGRICULTURE
FOOD & MARKETS - PESTICIDE RULES

12.04 (A) (2) - SURFACE CURBED OR WITH SUFFICIENT
SLOPE TO CATCH BASIN

12.04 (A) (3) - SURFACE & CATCH BASIN SIZED FOR
125 PERCENT CAPACITY OF THE LARGEST MOBILE
CONTAINER USED



PROVIDE 8" CURB AT PERIMETER WALLS - TYPICAL ALL ROOMS
FLOORS WILL HAVE 2% PITCH TO ALL SUMP PUMPS




DOOR TYPES

DOOR A - 3'-0"x6'-8", FIBERGLASS INSULATED,
LEVER HARDWARE, 1/2 GLASS
DOOR F - 12'-0"x12'-0", METAL INSULATED
OVERHEAD DOOR (R-17), MANUAL OPERATION
OR POWERED
DOOR H - 8'-0" X 10'-0" METAL INSULATED
OVERHEAD DOOR (R-17), MANUAL OPERATION

ENERGY CODE REVIEW

BELOW GRADE WALLS
CONCRETE FOUNDATION, CONDITIONED
(R-15 CONTINUOUS)
FLOOR TYPES
SLAB-ON-GRADE, CONDITIONED AT RADIANT
HEAT, INSULATE ENTIRE AREA UNDER RADIANT (R-20)
WALL TYPES
EXTERIOR, CONDITIONED (R-13+R-17
CONTINUOUS -or- R-22.1 CONTINUOUS)
ROOF TYPES
CONDITIONED (R-40 CONTINUOUS ABOVE DECK
-or- R-25 + R-11 + R-11 LINER SYSTEM)



STATE OF VERMONT AGENCY OF NATURAL
RESOURCES - ABOVE GROUND STORAGE TANK RULES
9-304 (A): INSTALLATION TO FOLLOW NFPA 1, NFPA
30 & 31 OR OTHER APPROVED METHOD

9-304 (C) (1): TANK SYSTEM PROTECTED FROM
SNOW & ICE BY ROOF OR SECONDARY CONTAINMENT

9-304 (C) (2): CONCRETE PAD TO BE MIN 4" THICK
AND EXCEED TANK DIMENSIONS BY 10%

NFPA 1
42.3.3.6 PHYSICAL PROTECTION FOR ALL OUTSIDE
ABOVEGROUND TANKS
(.1) CHAIN LINK FENCE AT LEAST 6' HIGH
(.2) 10' BETWEEN FENCE AND TANKS
(.3) SECURE GATE

NFPA 1
42.3.3.1.7 SPILL CONTROL FOR ABOVEGROUND
TANKS NOT IN VAULT TO COMPLY WITH NFPA 30

NFPA 30
22.11
SECONDARY CONTAINMENT-TYPE ABOVEGROUND
STORAGE TANK OR IMPOUNDING

CODE REVIEW

NEW CONSTRUCTION

APPLICABLE CODES

2015 VERMONT FIRE & BUILDING SAFETY CODE
(VT AMENDMENTS TO APPLICABLE CODES)
2015 IBC
2015 NFPA 101 LIFE SAFETY CODE
2015 NFPA 1
2017 VERMONT ELECTRICAL RULES
2018 VERMONT PLUMBING RULES
2012 VERMONT ACCESS RULES (VT
AMENDMENTS TO ADA)
2010 ADA AMERICANS WITH DISABILITY ACT
ACCESSIBILITY STANDARDS
2020 VERMONT ENERGY CODE

CONSTRUCTION TYPE

2B

OCCUPANCY CLASSIFICATION

STORAGE - IBC CHAPTER 3, MODERATE HAZARD
STORAGE GROUP S-1 & LOW HAZARD STORAGE
GROUP S-2/ NFPA 101 CHAPTER 42, STORAGE
OCCUPANCIES, LOW & ORDINARY HAZARD

OCCUPANCY LOAD

MAX PROBABLE POPULATION - NFPA 101, 42.1.7

HEIGHT & AREA

ALLOWABLE AREA (NON-SPRINKLERED) - 17,500
SF - IBC TABLE 506.2
PROPOSED AREA (NON-SPRINKLERED) - 3,305 SF
ALLOWABLE BUILDING HEIGHT IN FEET ABOVE
GRADE PLANE (NON-SPRINKLERED) - 55 FT - IBC
TABLE 504.3
PROPOSED BUILDING HEIGHT
(NON-SPRINKLERED) - 16'-6"
ALLOWABLE # OF STORIES (NON-SPRINKLERED) -
2 - IBC TABLE 504.4
PROPOSED # OF STORIES (NON-SPRINKLERED) - 1

**FIRE RESISTANCE RATING REQUIREMENTS FOR
BUILDING ELEMENTS**

(PRIMARY STRUCTURAL FRAME,
EXTERIOR/INTERIOR BEARING WALLS,
EXTERIOR/INTERIOR NON-BEARING WALLS,
FLOOR, ROOF)
ALLOWABLE RATING IN HOURS - 0 - IBC TABLE
601
PROPOSED RATING IN HOURS - 0

FIRE SEPARATION OF OCCUPANCIES

NONE

NUMBER OF EXITS

ALLOWABLE # OF EXITS - 1 PER SECTION IF
COMMON PATH OF TRAVEL IS LESS THAN 50 FT -
NFPA 101, 42.2.4.1 W/ TABLE 42.2.5
PROPOSED # OF EXITS STORAGE - 1 PER SECTION

REVISION DATE: 10/10/2023
PRINT DATE: 10/10/2023

#	Revisions	By
1	15-16-2023	RM
2	5-19-2023	RM
3	5-30-2023	RM
4	6-6-2023	RM
5	6-8-2023	RM

BUILDING "C" ENVIRONMENTAL
MANAGEMENT CENTER
FLOOR PLAN & ELEVATIONS


STOWE COUNTRY CLUB
TURF CARE CENTER
Stowe, Vermont

930 East Barre Rd.
P.O. Box 449
East Barre, Vermont 05649
P: 802-479-1078
F: 802-479-1070



FLOOR PLAN &
ELEVATIONS
Date: 4-27-2023
Scale: 3/16" = 1'-0"
Drawn By: RM

A3



- | | | | |
|------|-----------------------------------------------------------------------|-------|------------------------------------------|
| ⊕ | RAB DOWN CAST WALL PACK WITH PHOTO CELL | HB | HIGH BAY LED |
| △ | DATA PORT | HBOCC | HIGH BAY LED WITH OCC SENSOR |
| ⊕ | DUPLEX ⊕ 20 AMP | DISCO | DISCONNECT FOR EXHAUST FANS |
| ⊕ | QUAD ⊕ 20 AMP | 220 L | LIFT POWER |
| LED | 2' X 4' SATCO FLAT PANEL | 220 W | WELDER |
| OCC | CEILING MOUNT OCCUPANCY SENSOR | 220 C | COMPRESSOR |
| OCCS | WALL MOUNT OCCUPANCY SENSOR | ES | EMERGENCY STOP/DISCONNECT FOR FUEL PUMPS |
| 4 | 4' LED STRIP LIGHT | 120 H | HOT WATER ON DEMAND 12V |
| FAN | PANASONIC WHISPER GREEN SELECT FAN WITH OCCUPANCY SENSOR & HUMIDISTAT | □ | LIGHT FIXTURE |
| WP | WEATHER PROOF RECEPTACLE | | |
| GD ⊕ | GARAGE DOOR | | |
| S3 | THREE WAY SWITCH | | |
| S5 | SINGLE POLE SWITCH | | |
| EM | EMERGENCY LIGHT | | |
| EX | EXIT/EMERGENCY | | |
| CR | CORD REEL | | |
| ⊕ | 20 AMP 120V RECEPTACLE | | |

DATED: 7/6/2023
 PRINT DATE: 10/10/2023



#	Revisions	By
1		
2		
3		
4		
5		

BUILDING "A" ENVIRONMENTAL
 MANAGEMENT CENTER
 ELECTRICAL PLAN

STOWE COUNTRY CLUB
 TURF CARE CENTER
 Stowe, Vermont


TANNER ELECTRIC LLC

ELECTRICAL PLAN
 Date: 6-26-2023
 Scale: 1/8" = 1'-0"
 Drawn By: MT



SEPTIC POWER WITH EXPLOSION PROOF & DISCONNECT ON POST

⊕ 50 AMP GENERATOR RECEPTACLE



PROVIDE 8" CURB AT PERIMETER WALLS - TYPICAL ALL ROOMS FLOORS WILL HAVE 2% PITCH TO ALL SUMP PUMPS

#	Revisions	By
1		
2		
3		
4		
5		


BUILDING "C" ENVIRONMENTAL
MANAGEMENT CENTER
ELECTRICAL PLAN

STOWE COUNTRY CLUB
TURF CARE CENTER
Stowe, Vermont

TANNER ELECTRIC LLC

ELECTRICAL PLAN
Date: 6-26-2023
Scale: 1/4" = 1'-0"
Drawn By: MT

E2



DATED: 7/6/2023
 PRINT DATE: 10/10/2023

#	Revisions	By
1		
2		
3		
4		
5		

**BUILDING "A" ENVIRONMENTAL
 MANAGEMENT CENTER
 PLUMBING & HVAC PLAN**

**STOWE COUNTRY CLUB
 TURF CARE CENTER**
 Stowe, Vermont

**P&C PLUMBING
 AND HEATING**



PLUMBING & HVAC
 Date: 6-26-2023
 Scale: 1/8" = 1'-0"
 Drawn By: MP & DC

MI

#	Revisions	By
1		
2		
3		
4		
5		

BUILDING "C" ENVIRONMENTAL
MANAGEMENT CENTER
PLUMBING & HVAC PLAN


STOWE COUNTRY CLUB
TURF CARE CENTER
Stowe, Vermont

P&C PLUMBING
AND HEATING




PLUMBING & HVAC
Date: 6-26-2023
Scale: 1/4" = 1'-0"
Drawn By: MP & DC

M2



PROVIDE 8" CURB AT PERIMETER WALLS - TYPICAL ALL ROOMS
FLOORS WILL HAVE 2% PITCH TO ALL SUMP PUMPS

DATED: 7/6/2023
PRINT DATE: 10/10/2023




DATED: 10/10/2023
 PRINT DATE: 10/10/2023

#	Revisions	By
1		
2		
3		
4		
5		

BUILDING "A" ENVIRONMENTAL
 MANAGEMENT CENTER
 DRAINAGE PLAN


STOWE COUNTRY CLUB
 TURF CARE CENTER
 Stowe, Vermont

930 East Barre Rd.
 P.O. Box 449
 East Barre, Vermont 05649
 P. 802-479-1078
 F. 802-479-1070



PLUMBING & HVAC
 Date: 6-26-2023
 Scale: 1/8" = 1'-0"
 Drawn By: MP & DC

PI



PROVIDE 8" CURB AT PERIMETER WALLS - TYPICAL ALL ROOMS
 FLOORS WILL HAVE 2% PITCH TO ALL SUMP PUMPS

#	Revisions	By
1		
2		
3		
4		
5		

BUILDING "C" ENVIRONMENTAL
 MANAGEMENT CENTER
 PLUMBING FOR CARBTROL SYSTEM

STOWE COUNTRY CLUB
 TURF CARE CENTER
 Stowe, Vermont

CARBTROL CORP.

PLUMBING & HVAC
 Date: 6-26-2023
 Scale: 1/4" = 1'-0"
 Drawn By: MP & DC

P2



3 - Rendering Northeast View from Cape Cod Road



4 - Rendering of Northwest View from Cape Cod Road



Stowe Country Club-Turf Care Center

Spill Prevention Control and Countermeasures (SPCC)

Current Spill Prevention Control and Countermeasures (SPCC) systems:

- Currently have a SPCC Plan. Please see Attachment D.
- The Equipment wash area at the east end of the site currently utilizes a 25-foot vegetative buffer to filter wash water before entering the drainage way (Attachment A). This is an acceptable practice. However, it is not the best approach.
 - The drainage way discharges to a culvert under Cape Cod Road and into the West Branch Little River
- The Pesticide/fertilizer mix and load area utilizes the 25-foot vegetative buffer before reaching the drainage way. This is an acceptable practice. However, it is not the best approach.
- Pesticide/fertilizer storage has minimal containment ability. This is currently Stored in the wooden shed (See Attachment B) located between the house and handball court building.
- Maintenance equipment is stored in a tent with a gravel base (See Attachment C) . This is not a preferred method for spill containment.
- Fuel storage has concrete tanks for secondary containment and are double walled.

Proposed New Turf Care Center SPCC Systems:

- The construction of this redeveloped facility will enable the SPCC Plan updated to reflect the improved systems.
- Equipment washing will utilize the Carbtrol System. This is a closed loop system. Carbtrol utilizes carbon and sand filters with hydrogen peroxide purification as the method of treatment. Zero potential for off-site runoff. Please see Attachment E, the attached system description. This system is currently utilized at the Stowe Mountain Golf Club Turf Care Facility.
- Pesticide/fertilizer mix and load area will be located in a room with a concrete curbed floor.
 - The floor is pitched to a center drain.
 - The Center drain will have a gate valve to provide the ability to utilize storage capacity of sloped floor and center sump drain (300 gallons).

Spill Prevention Control and Countermeasures (SPCC)

- A 500-gallon empty storage tank will be utilized if any large spill occurs.
 - Redundant spill containment capacity is provided by the Carbtrol system (500 gallons).
 - Day to day small spills are captured and cleaned by the Carbtrol system.
 - Zero potential for off-site runoff.
- Pesticide/fertilizer storage is in the mix and load room and adjacent to the fertilizer storage room.
 - These rooms have concrete curbed floors with center sump drains piped to the Carbtrol system.
 - Sloped floor capacity and Carbtrol system are utilized for secondary spill containment.
 - Golf course equipment will be stored in areas with concrete floors. This will allow for best spill containment.
 - Fuel storage will utilize double walled tanks for primary containment. In addition, they are stored on a concrete sloped floor with a center drain.
 - This center drain is piped to the Carbtrol system.
 - Day to day small fuel spills are captured and cleaned by the Carbtrol system.
 - Large spills will utilize the storage capacity of the Carbtrol System (500 gallons)

The goal of this system is to replace an unenclosed system with a fully enclosed system, consolidated within the new building, that will be provided a significant reduction in any chance of discharges leaving the property and migrating to the West Branch.

Supplementary Systems

1. The Turf Care Maintenance Facility (Building A) **floor drain system** is collected and conveyed to a 1000-gallon storage tank located on the east end of the building.
 - a. The storage tank is outfitted with a water level alarm which is triggered when 80% of the storage capacity is met.
 - b. When the fill condition is met, the contents are pumped by a local hauler for disposal at a certified facility.

Again, the goal is to create a fully enclosed system with no design discharges to the surrounding environment.



Attachment A - Existing Vegetative Buffer at Equipment Wash-off Area



CAUTION
Pesticide Storage
Flammables

B - Existing Pesticide Storage Facility



Attachment C - Existing Equipment Storage

**REPORT ON
SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN
STOWE COUNTRY CLUB GOLF COURSE MAINTENANCE FACILITY
STOWE, VERMONT**

by Haley & Aldrich, Inc.
Bedford, New Hampshire

for Stowe Country Club
Stowe, Vermont

File No. 131315-005
June 2022

Attachment D - SPCC Plan-Stowe Country Club-Final





HALEY & ALDRICH, INC.
3 Bedford Farms Drive
Bedford, NH 03110
603.625.5353

28 June 2022
File No. 131315-005

Stowe Country Club
7412 Mountain Road
Stowe, Vermont 05672

Attention: Kevin Komer, CGCS
Director of Agronomy

Subject: Spill Prevention Control and Countermeasures Plan
Stowe Country Club Golf Course Maintenance Facility
Stowe, Vermont

Ladies and Gentlemen:

Please find one hard copy and an electric copy of the Spill Prevention Control and Countermeasures Plan, developed by Haley & Aldrich, Inc. for the Stowe Country Club Golf Course Maintenance Facility located at 418 Cape Cod Road in Stowe, Vermont. If you have any questions or comments regarding the plan, please contact the undersigned at 617.886.7580.

Sincerely yours,
HALEY & ALDRICH, INC.

Jessica Wey
Staff Engineer

Douglas M. Lindsay, P.G. (NH), LSP (MA)
Associate | Senior Project Manager

Jeffery A. Miller, P.E.
Associate | Senior Project Manager

Enclosures

\\haleyaldrich.com\share\man_common\131315_Stowe\005 Stowe Country Club SPCC Plan\SPCC Plan\Text\2022-0628-HAI-SPCC Plan-Stowe Country Club-F.docx

Employees' Responsibility to Report Oil Spills

Any release of oil at the Stowe Country Club Golf Course Maintenance Facility requires IMMEDIATE REPORTING to the SPCC Coordinator, Alternate Coordinators, or Night Shift Coordinators. If you are unable to immediately reach a Coordinator, you should instead report the oil release to Vermont Department of Environmental Conservation (VDEC).

SPCC Coordinator: Kevin Komer 802.253.3458 - office
Director of Agronomy 802.793.9108 - cell

Alternate Coordinator: Andrew Chuber 913.683.8831 - cell
Equipment Manager

The Lodge at Spruce Peak Spruce Loss Prevention 802.760.4760 - office
802.461.6690 - cell

VDEC 802.828.1138 and
800.641.5005

The SPCC Coordinator or Alternate in conjunction with Senior Management will determine the appropriate actions to respond to the release and will supervise the response.

SPCC Coordinators' Responsibility to Report Oil Spills

The SPCC Coordinator in conjunction with Senior Management will determine if an oil spill incident requires notification of federal and/or state officials. If the oil spill causes a sheen on surface waters or a violation of water quality standards, the U.S. Environmental Protection Agency (EPA) National Response Center (NRC) must be contacted at the phone number below. Small, incidental releases of oil (less than 2 gallons) that do not affect surface waters and that are expeditiously contained and cleaned up are not required to be reported to Vermont Department of Environmental Conservation (VDEC); nevertheless, the SPCC Coordinator has the discretion to report such releases. All other oil spills must be reported to VDEC.

At any time of day or night, contact NRC at **800.424.8802**.

Contact VDEC at **802.828.1138** and **800.641.5005**.

“**Oil**” is oil of any kind in any form, including but not limited to crude oil, petroleum, petroleum-refined products, fuel oil, sludge, oil refuse, and oil mixed with wastes other than dredged spoil. The term also includes non-petroleum oils such as vegetable and animal oils.

When notifying VDEC and/or NRC of confirmed or suspected releases of oil, provide as much of the following information as is available:

- Exact address or location and phone number of the facility;
- The date and time of the release;
- The type of material released;
- Estimate of the total quantity released;
- The source of the release;
- A description of all affected media;
- The cause of the release;
- Any damages or injuries caused by the release;
- Actions being taken to stop, remove, and mitigate the effects of the release;
- Whether an evacuation may be needed;
- The names of individuals and/or organizations who have also been contacted; and
- Name and location of receiving waters, (if applicable).

Whenever a facility has discharged more than 1,000 gallons of oil in a single spill event, or discharged more than 42 gallons of oil in each of two spill events within any twelve-month period, then the SPCC Plan Coordinator in conjunction with Senior Management shall submit the following to the Regional Administrator (EPA, Region 1), or their designee, within 60 days:

- Name of the facility;
- Your name;
- Location of the facility;

- Maximum storage or handling capacity of the facility and normal daily throughput;
- Corrective action and countermeasures you have taken, including a description of equipment repairs and replacements;
- An adequate description of the facility, including maps, flow diagrams, and topographical maps, as necessary;
- The cause of such discharge as described in federal regulation 40 Code of Federal Regulations (CFR) 112.1(b), including a failure analysis of the system or subsystem in which the failure occurred;
- Additional preventive measures you have taken or contemplated to minimize the possibility of recurrence; and
- Such other information as the Regional Administrator may reasonably require pertinent to the Plan or discharge.

A copy of this information must also be submitted to the VDEC.

Additional Emergency Contact Phone Numbers:

Stowe Fire Department	911
Stowe Police Department	911
Stowe Rescue and Hazardous Terrain	911
The Lodge at Spruce Peak Spruce Loss Prevention	802.760.4760 - office 802.461.6690 - cell
Environmental Products and Services (cleanup contractor)	1.800.577.4557 802.862.1212 (Vermont)

Table of Contents

	Page
Employees' Responsibility to Report Oil Spills	i
SPCC Coordinators' Responsibility to Report Oil Spills	ii
List of Tables	vi
List of Figures	vi
1. Introduction	1
1.1 PLAN ADMINISTRATION	1
1.1.1 SPCC Plan Coordinators	1
1.1.2 Plan Amendments	2
1.1.3 Review and Re-certification of Plan	2
1.1.4 Submission of Plan	2
1.1.5 Locations of Plan	3
1.2 DESCRIPTION OF FACILITY	3
1.3 SURFACE WATER DRAINAGE	4
1.4 OIL STORAGE INVENTORY	4
1.4.1 Exterior Gasoline and Diesel Fuel ASTs	4
1.4.2 Olsen House Heating Fuel AST	5
1.4.3 Barn Equipment Storage Area Drums	5
1.4.4 Shop Area Drums	5
1.4.5 Oil-filled Electrical Equipment	5
1.5 OIL SPILL HISTORY	5
1.6 POTENTIAL SPILL/RELEASE SOURCES	5
1.6.1 Bulk Fuel Loading	5
1.6.2 Vehicle and Equipment Fueling	6
1.6.3 Leaky Valves or Piping	6
1.6.4 Tank Failure, Rupture, or Puncture	6
1.6.5 Mishandling of Drums	6
1.7 VOLUME AND FLOW PREDICTIONS	6
1.7.1 Bulk Fuel Loading	6
1.7.2 Vehicle and Equipment Fueling	7
1.7.3 Leaking Valve or Pipe	7
1.7.4 Tank Failure, Rupture, or Puncture	7
1.7.5 Mishandling of Drums	7
2. Spill Containment and Equipment	8
2.1 COMPATIBILITY OF TANKS AND STORED MATERIALS	8
2.1.1 Best Management Practices for New or Updated Tank Installations	8
2.1.2 Existing Tanks	8
2.2 TRANSFER OPERATIONS	9
2.3 TANK TRUCK UNLOADING PROCEDURES	9
3. Spill Countermeasures	10

Table of Contents

	Page	
3.1	SMALL, INCIDENTAL RELEASES OF OIL	10
3.2	OTHER RELEASES OF OIL	10
3.2.1	Oil Spill Contingency Plan	10
3.2.2	Facility Evacuation Plan	13
3.2.3	Duties and Responsibilities of the SPCC Coordinator	13
3.3	SPILL RESPONSE AND PERSONAL PROTECTIVE EQUIPMENT	13
3.4	SPILL RESPONSE CONTRACTOR	14
3.5	SPILL REPORTING	14
3.5.1	Federal Reporting	14
3.5.2	State Reporting	14
4.	Inspections, Tests, and Records	15
4.1	GENERAL REQUIREMENTS	15
4.2	SPECIFIC TESTING AND INSPECTION REQUIREMENTS	15
4.2.1	Tank Testing Requirements	15
4.2.2	Transfer Piping Inspection Requirements	15
4.3	INSPECTION OF OIL STORAGE CONTAINERS, TANKS, AND PIPING	16
4.3.1	Monthly Inspections	16
5.	SPCC Training	17
6.	Security	18
7.	Conformance to Applicable Federal SPCC Standards	19
8.	Plan Certifications	20
8.1	PROFESSIONAL ENGINEER CERTIFICATION	20
8.2	FACILITY CERTIFICATION	20
9.	Cross-Reference to SPCC Plan Regulations	21

Tables

Figures

Appendix A – SPCC Plan Review Log

Appendix B – Example Sheen Inspection Log

Appendix C – Fueling Procedures

Appendix D – Stowe Employee Spill Response Procedure

Appendix E – Example SPCC Inspection Forms

Appendix F – Photo Log

List of Tables

Table No.	Title
I	Summary of Oil Storage and Use
II	Prediction of Potential Oil Releases
III	SPCC Rule Cross-Reference

List of Figures

Figure No.	Title
1	Project Locus
2	Site Plan – Stowe Country Club Golf Course Maintenance Facility

1. Introduction

This Spill Prevention Control and Countermeasures (SPCC) Plan is required for the Stowe Country Club Golf Course Maintenance Facility (the site) because the aboveground oil storage capacities at the resort are greater than the applicability thresholds under the federal SPCC regulations (40 Code of Federal Regulations [CFR] 112). An SPCC Plan is required for facilities which have an aggregate aboveground storage capacity of oil greater than 1,320 gallons or a completely buried storage capacity of oil greater than 42,000 gallons. Upon the installation of two new 500-gallon aboveground storage tanks (ASTs; replacing existing 350-gallon ASTs) during the summer of 2022, Stowe Country Club Golf Course Maintenance Facility's aboveground oil storage capacity will be approximately 1,495 gallons. Stowe Country Club does not own or operate underground storage tanks (USTs).

This plan has been prepared in accordance with good engineering practices. This SPCC Plan has the full approval of management to commit the necessary resources to fully implement the plan. Section 9 provides a cross-reference of the sections of 40 CFR 112.7 and 112.8 to the applicable sections in this plan.

1.1 PLAN ADMINISTRATION

1.1.1 SPCC Plan Coordinators

The SPCC Plan coordinators for Stowe Country Club are:

Primary Coordinator:

Kevin Komer
Director of Agronomy
Stowe Country Club Golf Course Maintenance Facility
418 Cape Cod Road
Stowe, Vermont 05672
Office Phone: 802.253.3458
Cell Phone: 802.793.9108

The Primary Coordinator is responsible for overall administration of this SPCC Plan, including amendments, certifications, reporting, recordkeeping, training, and spill response.

Alternate Coordinators:

The Equipment Manager of Stowe Country Club, Andrew Chuber, is the Alternate SPCC Coordinator. Please see the cover sheet that identifies names and phone numbers of each coordinator.

The Alternate Coordinator is responsible for coordinating inspections and assisting the Primary Coordinator with spill response and maintaining records of inspections and spill incidents.

The Lodge at Spruce Peak Loss Prevention is also listed on the cover sheet and will be responsible for coordinating oil spill response activities if a release is detected during off hours.

1.1.2 Plan Amendments

This SPCC Plan must be amended whenever there is a change in facility design, construction, operation, or maintenance which materially affects the facility's potential for the discharge of oil into or upon the navigable waters of the United States or adjoining shorelines (40 CFR 112.5(a)). Such changes may include, but are not limited to:

- addition to or reduction of oil storage capacity;
- replacement, reconstruction, or movement of containers or piping systems;
- changing types of oil materials stored, used, or generated;
- modifications to containment areas;
- drainage system modifications; or
- revisions of standard operations or maintenance procedures at a facility.

An amendment made under this section must be prepared within six months, and implemented as soon as possible, but not later than six months following preparation of the amendment. A registered Professional Engineer must certify all non-administrative amendments to the plan.

1.1.3 Review and Re-certification of Plan

Regardless of whether changes have occurred at the facility, this SPCC Plan must also be reviewed and evaluated at least once every five years (40 CFR 112.5(b)). As a result of this action, the SPCC Plan must be amended within 6 months to include more effective prevention and control technology if such technology will significantly reduce the likelihood of a spill event at the facility, as long as such technology has been field-proven at the time of the review. The plan shall also be amended to reflect changes in the facility, as described above. The technical amendments to the SPCC Plan must be re-certified by a registered Professional Engineer.

The five-year SPCC Plan review and evaluation must be documented by signing a statement as to whether the Plan will be amended. The following statement will suffice: *"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on (date) and will (will not) amend the Plan as a result."* This statement must be included in the plan (Appendix A).

1.1.4 Submission of Plan

A copy of this SPCC Plan must be maintained and accessible at the Stowe Country Club Golf Course Maintenance Facility and shall be made available to the Regional Administrator of the U.S. Environmental Protection Agency (EPA), or his designee, if requested. This plan does not, under typical circumstances, have to be submitted to the EPA or to the Vermont Department of Environmental Conservation (VDEC).

However, whenever a facility has discharged more than 1,000 gallons of oil in a single spill event, or discharged more than 42 gallons of oil in each of two spill events within any twelve-month period, then the SPCC Plan Coordinator shall submit the following to the Regional Administrator (EPA, Region 1), or his designee, within 60 days:

- Name of the facility;

- Your name;
- Location of the facility;
- Maximum storage or handling capacity of the facility and normal daily throughput;
- Corrective action and countermeasures you have taken, including a description of equipment repairs and replacements;
- An adequate description of the facility, including maps, flow diagrams, and topographical maps, as necessary;
- The cause of such discharge as described in 40 CRF 112.1(b), including a failure analysis of the system or subsystem in which the failure occurred;
- Additional preventive measures you have taken or contemplated to minimize the possibility of recurrence; and
- Such other information as the Regional Administrator may reasonably require pertinent to the Plan or discharge.

A copy of this information must also be submitted to the VDEC.

If, after review by the agencies, the SPCC Plan is required to be amended, such amendments to the plan must be made within 30 days of notification. Amendments must be implemented as soon as possible, but not later than six months after the amendments become part of the plan (unless other dates are specified in the notice).

Note: Additional details regarding the requirements and deadlines for Plan submittal are located in 40 CFR 112.4 (a) through (f).

1.1.5 Locations of Plan

A copy of this SPCC Plan must be maintained at the Stowe Country Club Golf Course Maintenance Facility and shall be made available to the VDEC and the Regional Administrator of the EPA, if so requested. Copies of this SPCC Plan are maintained at the following locations (or with the following individuals):

1. Kevin Komer, Director of Golf Maintenance, Primary SPCC Coordinator; Stowe Country Club Golf Course Maintenance Facility
2. Andrew Chuber, Equipment Manager, Alternate SPCC Coordinator; Stowe Country Club Golf Course Maintenance Facility

1.2 DESCRIPTION OF FACILITY

Stowe Country Club is an approximately 175.5-acre recreational facility located approximately one mile northwest of the town of Stowe, in Lamoille County, Vermont off Cape Cod Road (Figure 1). Stowe Country Club comprises a golf course and a maintenance facility which is the focus of the SPCC Plan.

Site activities related to the storage and handling of oil include:

- Equipment fueling – gasoline and diesel fuel

- Building heat – fuel oil
- Drums – hydraulic oil, engine oil, motor oil, and waste oil
- Oil-filled electrical equipment – hydraulic oil

1.3 SURFACE WATER DRAINAGE

Water from storm events and snow melt from the mountain peaks is conveyed generally east from the Mt. Mansfield area and generally south from the Stowe Country Club area via unnamed brooks and intermittent streams to the West Branch of the Waterbury River (presently known as West Branch Little River). The West Branch Little River is located approximately 150 feet south of the subject site across Cape Cod Road. Drainage from the equipment washing area on the eastern side of the maintenance facility area is conveyed east to a grassy area using a swale. Surface runoff from the Stowe Country Club Golf Course is conveyed to various small ponds located throughout the course.

1.4 OIL STORAGE INVENTORY

A list of oil storage locations regulated under this SPCC Plan is provided in Table I. The list includes the following information:

- Building or other location;
- Inside or outside storage;
- Type of container or tank (underground storage tank, aboveground storage tank, transformer, drum, etc.);
- VT UST Registration Number, if applicable;
- Container/tank capacity;
- Tank contents;
- Containment; and
- Presence of storm drains or surface water in the vicinity.

A brief description of the locations of oil stored at the Stowe Country Club Golf Course Maintenance Facility follows. Figure 1 is a Project Locus map. Figure 2 is a Site Plan that identifies oil storage locations. Structural and non-structural controls implemented to prevent and contain oil spills are described in Section 3 of the plan.

1.4.1 Exterior Gasoline and Diesel Fuel ASTs

Two 350-gallon single-wall steel ASTs, containing diesel fuel and gasoline, are currently located in the northwest corner of the site adjacent to a material pile storage area (Figure 2). The two ASTs have a secondary containment structure and are used to fuel equipment such as lawn mowers used on the golf course. The ASTs appear to be in good condition, and the containment structures do not have signs of oil leakage from the tank. No nearby drains exist in the area.

During the summer of 2022, the two 350-gallon ASTs will be replaced by two 500-gallon ASTs, and they will still contain diesel fuel and gasoline. The 500-gallon ASTs will be double-walled so secondary containment will not be required. Per the recommendation from the Vermont State Fire Marshal, the two 500-gallon ASTs will have a roof covering.

1.4.2 Olsen House Heating Fuel AST

One 275-gallon single-wall steel AST containing #2 heating oil is located within the basement of the Olsen House and is used for building heat (Figure 2). The tank has a secondary containment structure, and no drains exist in the basement area. The tank appears to be in good condition, and the secondary containment structure does not show signs of oil leakage from the tank.

1.4.3 Barn Equipment Storage Area Drums

Three 55-gallon drums containing hydraulic oil, motor oil, and waste oil are located within the Barn Equipment Storage Area (Figure 2). The drums are stored on portable spill containment pallets. Only two of the drums at a time are filled with oil, and the third drum is used as backup storage. No drains exist in the barn equipment storage area. Various 5-gallon buckets are stacked around the drums. Three of the buckets are full and contain gear oil, auto transmission fluid, and hydraulic fluid.

1.4.4 Shop Area Drums

Two 55-gallon drums containing engine oil and hydraulic oil are located within the shop area adjacent to the flammable storage cabinet (Figure 2). The drums are stored on portable spill containment pallets. No drains exist in the shop area.

1.4.5 Oil-filled Electrical Equipment

1.4.5.1 Hydraulic Lift

A hydraulic lift containing 12 quarts of hydraulic oil in the reservoir is located within the shop area nearby the 55-gallon drums and flammable storage cabinet (Figure 2). The lift appears to be in good condition with no signs of oil leakage.

1.5 OIL SPILL HISTORY

According to site personnel and available records, large oil spills or oil releases in the 2- to 20-gallon range have not occurred at the Stowe Country Club Golf Course Maintenance Facility.

1.6 POTENTIAL SPILL/RELEASE SOURCES

The sources of potential oil releases at the Stowe Country Club Golf Course Maintenance Facility are listed below. This section is intended to provide the information required in section 112.7(b) [Fault Analysis] of the SPCC regulations. Controls and countermeasures implemented by Stowe Country Club Golf Course Maintenance Facility to mitigate or respond to potential releases to the environment are described in Sections 3 and 4, respectively. Potential release volumes, direction of flow, and ultimate discharge locations for reasonably foreseeable oil releases are included in Table II.

1.6.1 Bulk Fuel Loading

Fuel loading (adding fuel oil, diesel fuel, or gasoline to an AST or UST) occurs at the locations listed below by drainage area. Under the SPCC regulations, a “bulk storage container” is any container used to

store oil; oil-filled electrical equipment is an operational use of oil and is not included in the definition of bulk storage container.

- Exterior 500-gallon fueling gasoline and diesel fuel ASTs
- Interior Olsen House 275-gallon #2 heating oil AST

A release could occur at the AST or UST locations if the delivery truck's hoses are not properly connected, if hoses or valves fail, if disconnection is not properly performed (i.e., still pumping when hose is disconnected), or if the tank is overfilled due to failure of the high-level alarm.

1.6.2 Vehicle and Equipment Fueling

Facility equipment such as lawn mowers, tractors, and a 1-ton dump truck used on site can be fueled at the exterior gasoline and diesel fuel ASTs located in the northwest portion of the property. Fuel is transferred to vehicles using a typical service station fuel pump setup. A release could occur if the operator fueling the vehicle/equipment overfills a tank or if the automatic shutoff of the fuel nozzle fails.

1.6.3 Leaky Valves or Piping

Valves may leak if they are not entirely closed or may leak if they are old and/or corroded. Piping may leak due to corrosion or through fittings. Generally, leaks of these types are slow and will likely be mitigated through regular inspections. Quick connect piping systems are not currently used at Stowe Country Club.

1.6.4 Tank Failure, Rupture, or Puncture

A release from a tank (including aboveground fuel tanks, transformers) may occur if the tank integrity is weak (e.g., slow leak through a weld seam in a tank), or if the tank ruptures due to an outside force (e.g., vehicle hitting a tank). These scenarios are unlikely; however, they deserve attention due to the proximity of some of these tanks to surface waters.

1.6.5 Mishandling of Drums

Oil is stored in 55-gallon drums at the barn equipment storage area and shop area. A release of oil could occur at any of these facilities if a drum is knocked over or punctured during delivery or handling.

1.7 VOLUME AND FLOW PREDICTIONS

Table II includes a summary of maximum volume and ultimate discharge locations from tanks, equipment, and activities at the facility that present a reasonable potential for releasing oil in harmful quantities (meaning an amount capable of creating a sheen or violating surface water quality standards etc.) to waters of the United States. An example sheen inspection form is included as Appendix B.

1.7.1 Bulk Fuel Loading

As shown on Figure 2, bulk oil deliveries occur at the exterior gasoline and diesel fuel ASTs located in the northwest corner of the site. Trucks deliver fuel to these ASTs which are located on an unpaved surface

and within secondary containment once per week. Storm drains are not located proximate to oil tanks within the site boundary. If a release occurred from one of the exterior ASTs, oil could be conveyed across the parking lot to the entrance to the yard, into a vegetated ditch which leads to a 12-inch corrugated metal culvert within the Town of Stowe Right-of-Way (ROW). Because the Town ROW culvert leads directly to the West Branch Little River, a storm drain safety seal cover, mat, or plug should be applied during fuel loading to prevent potential spills from reaching the storm drain system that leads to surface water.

Bulk fuel loading occurs for the interior Olsen House #2 heating oil tank through an outside fill port approximately once per month. The fill port for the Olsen House AST is located on the western side of the Olsen House. A release during filling of the Olsen House heating oil tank would likely be contained within the basement area which does not have a floor drain.

1.7.2 Vehicle and Equipment Fueling

Facility equipment such as lawn mowers can be fueled at the exterior 500-gallon gasoline and diesel fuel ASTs located in the northwest portion of the property on an impervious surface.

1.7.3 Leaking Valve or Pipe

Leaky valves or piping could cause a release of oil from any one of a number of ASTs. Generally, these types of releases are small in volume and would be confined within secondary containment structures and detected during regular inspections. The actual volume of a release of this type should depend on the severity of the leak and the time it takes to discover the release.

1.7.4 Tank Failure, Rupture, or Puncture

A release of oil due to tank failures, ruptures, or punctures is an unlikely occurrence; however, due to the proximity of the ASTs to surface waters (West Branch Little River), contemplation of this type of release is warranted. A release of oil could occur if the welded seams for a tank are weak or corroded and eventually fail, or if a vehicle strikes a tank. Such a release scenario could result in a release of oil up to the maximum capacity of the tank.

1.7.5 Mishandling of Drums

Oil drums are typically stored and handled at the barn equipment storage area and shop area.

Mishandling of drums (e.g., dropping a drum during delivery, tipping over a drum, or puncturing a drum) could result in the release of the drum contents to the ground surface. If the release occurred within the confines of one of these buildings, engineering controls such as berms, floor drain plugs, portable spill control pallets, and dead-end sumps, coupled with operational controls such as spill absorbent materials readily at hand, would likely prevent the oil from discharging to the environment. A release occurring outside one of these buildings during drum handling activities (such as receiving virgin oil or shipping off used oil) would be subject to immediate response by the Spruce Peak personnel engaged in the activity.

2. Spill Containment and Equipment

2.1 COMPATIBILITY OF TANKS AND STORED MATERIALS

The material and construction of oil storage tanks and containers used at the Stowe Country Club Golf Course Maintenance Facility are compatible with the material stored and conditions of storage such as pressure and temperature.

2.1.1 Best Management Practices for New or Updated Tank Installations

If a field-constructed aboveground container undergoes a repair, alteration, reconstruction, or a change in service that might affect the risk of a discharge or failure due to brittle fracture or other catastrophe, or if it has discharged oil or failed due to brittle fracture failure or other catastrophe, an evaluation of the container for risk of discharge or failure due to brittle fracture or other catastrophe is performed. Based on this evaluation, appropriate action will be taken.

Each new or updated container installation will be performed in accordance with good engineering practice to avoid discharges. At least one of the following devices must be provided:

- High-liquid level alarm with an audible or visual signal at a constantly attended operation or surveillance station. In smaller facilities an audible air vent may suffice.
- High-liquid level pump cut-off devices set to stop flow at a predetermined container content level.
- Direct audible or code signal communication between the container gauge and the pumping station.
- A fast response system for determining the liquid level of each bulk storage container such as digital computers, telepulse, or direct vision gauges. If this alternative is used, a person must be present to monitor gauges and the overall filling of bulk storage containers.
- Liquid level sensing devices must be regularly tested to ensure proper operation.

2.1.2 Existing Tanks

2.1.2.1 Aboveground Storage Tanks

Two 350-gallon single-wall steel ASTs containing diesel fuel and gasoline are currently located within secondary containment in the northwest corner of the site adjacent to a material pile storage area. During the summer of 2022, the two 350-gallon ASTs will be replaced with two 500-gallon ASTs, and the new tanks will still contain diesel fuel and gasoline. The 500-gallon ASTs will be double-walled so additional secondary containment will not be required.

One 275-gallon single-wall steel AST containing #2 heating oil is located within a secondary containment structure in the basement of the Olsen House and is used for building heat.

2.1.2.2 *Oil-filled Electrical Equipment*

A hydraulic lift containing 12 quarts of hydraulic oil in the reservoir is located within the shop area nearby the 55-gallon drums and flammable storage cabinet.

2.1.2.3 *Drum Storage*

55-gallon drums are stored and handled at the Stowe Country Club Golf Course Maintenance Facility. Drums typically contain various equipment maintenance oils and lubricants and are stored on portable spill containment pallets. One 55-gallon sized spill kit containing spill equipment is located in the barn equipment storage area near the drums.

2.2 TRANSFER OPERATIONS

Piping transfers of oil at Stowe Country Club Golf Course Maintenance Facility include fuel oil transfers from exterior fueling ASTs and a #2 heating oil AST within the Olsen House to fuel burning equipment occur through aboveground single-wall piping.

2.3 TANK TRUCK UNLOADING PROCEDURES

Bulk deliveries of petroleum products at the Stowe Country Club Golf Course Maintenance Facility include delivery of gasoline, fuel oil, and diesel fuel. Fuel delivery schedules vary, depending on usage; however, all deliveries of fuel are made during hours when a Stowe Country Club employee, who has been trained in SPCC procedures, is on site during the delivery.

Bulk fuel delivery procedures include the following (refer to Appendix C for fueling procedures):

- Fuel service delivery truck driver notifies an authorized Stowe Country Club Golf Course Maintenance Facility representative one hour prior to delivery.
- The Stowe Country Club Golf Course Maintenance Facility representative advises the driver of road conditions and determines if access is clear.
- All fuel deliveries must occur between 6:00 a.m. and 6:00 p.m. unless exceptions to this schedule are approved by the Facility Equipment Manager.
- Pre-fueling inspections are conducted.
- Fueling is performed following satisfactory pre-fueling inspections.
- Visual inspection of fuel ports, for the presence of spills, and the tank level is performed.

3. Spill Countermeasures

Spill countermeasures are required for all spills ranging from small, incidental spills to large, catastrophic releases. Section 3.1 describes procedures to follow for incidental spills that do not require reporting to regulatory agencies (i.e., spills less than 2 gallons that are contained and do not affect surface waters). Section 3.2 includes procedures developed to respond to larger spills that require notification to regulatory agencies (i.e., spills greater than 2 gallons, or smaller spills that affect surface waters).

3.1 SMALL, INCIDENTAL RELEASES OF OIL

A small, incidental release of oil is one in which less than 2 gallons is released, surface waters are not affected, and the oil is expeditiously contained and cleaned up. Such a release is not subject to reporting to VDEC.

When such a release occurs, the cause of the release must be determined and fixed in a manner to mitigate further releases of oil. Contaminated materials resulting from the release (e.g., soil, speedy-dry, and/or sorbent pads/booms) must be contained, stored, and disposed of appropriately.

3.2 OTHER RELEASES OF OIL

A release of oil greater than 2 gallons, or a smaller release that adversely affects surface waters, requires reporting to the VDEC. If such a release violates applicable water quality standards or causes a sheen on the surface of the water, additional reporting to the EPA NRC is required.

Releases of oil that cannot be expeditiously contained and cleaned up by Stowe Country Club Golf Course Maintenance Facility personnel may necessitate implementation of the Oil Spill Contingency Plan (see below). The procedures in the Oil Spill Contingency Plan may be adjusted based on the severity of the release (e.g., amount released, and proximity to catch basins or surface waters).

3.2.1 Oil Spill Contingency Plan

3.2.1.1 *Spill Response Procedures*

If an imminent or actual emergency situation exists with respect to a release of oil, the SPCC Coordinator or his designee will be contacted immediately. The SPCC Coordinator is responsible for coordinating all emergency response measures and has the authority to commit all resources required to implement the emergency response procedures in this SPCC Plan.

The SPCC Coordinator must have complete knowledge of:

- This SPCC Plan;
- Property layout;
- All operations and activities at the property, and the location and characteristics of oil stored and used on site; and
- Location of relevant records within the facility.

The following actions shall be taken by the SPCC Coordinator during a release event. These actions may be modified based on the severity of the release.

- A. Situation Assessment - The SPCC Coordinator shall immediately identify the character, exact source, amount, and real extent of any released materials. He/she may do this by observation, knowledge, and review of facility records, and if necessary, through chemical analysis.
- B. Situation Evaluation - Concurrently, the SPCC Coordinator must evaluate the potential threat to human health or to the environment presented by the situation. This assessment must consider both direct and indirect effects of the release, including fire or explosion (e.g., the effects of any toxic, irritating, or asphyxiating gases that are generated, or the effects of any hazardous surface water runoffs from water or chemical agents used to control fire or heat-induced explosions).
- C. Safe Distances and Refuge - The SPCC Coordinator will determine safe distances from an oil spill after identifying the type of oil and quantity spilled and an evaluation of the potential health and safety impact to the employees and/or guests in the vicinity of the spill area. If necessary, the SPCC Coordinator may initiate a local evacuation around the spill area or a facility evacuation (See Section 3.2.2).
- D. Agency Notifications - The SPCC Coordinator or his designee is responsible for making required notifications to federal, state, and local agencies. If the SPCC Coordinator determines that the situation poses a potential threat to human health or the environment, or additional resources are needed to assist in the response, local authorities (Stowe Police and Fire Departments) will be notified immediately.
- E. Site Security and Control - Once the spill area has been identified and employees have been evacuated (if necessary), the site boundaries must be clearly defined. Every effort shall be made to define the spill area using physical barriers (e.g., walls, doors, and/or cones). When physical barriers are not suitable for defining the spill area, caution tape shall be used to mark locations for restricted access. Only those personnel directly involved with spill activities will be permitted to enter the area. Boundaries will be defined for three specific locations as noted below in order of increasing proximity to the spill:
 - Support Zone: Restricted area defining the outer boundary of spill response activities. All necessary response personnel, tools, and equipment will be within the Support Zone. Access is restricted to spill response personnel.
 - Contamination Reduction Zone: This is the decontamination area. The Contamination Reduction Zone shall be placed between the Exclusion Zone (see below) and Support Zone. Access is restricted to decontamination personnel and trained spill responders entering or exiting the Exclusion Zone. Decontamination personnel shall be equipped with necessary personal protective equipment (see Section 3.3) to guard them from contaminants that may be present on materials and spill response personnel leaving the Exclusion Zone. The Contamination Reduction Zone shall be continually manned during spill response activities. Activities in this area are confined to those necessary to minimize contamination of any object or person leaving the Exclusion Zone and the spread of contamination outside the Exclusion Zone.

- Exclusion Zone: This is the spill area. Access is restricted to trained spill responders with appropriate personal protection to guard against the spilled material. Activity within this area is confined to hazard control, spill characterization, and cleanup activities. Movement of personnel from the Support Zone into the Exclusion Zone shall be permitted only under instruction from the SPCC Coordinator. All such movement will be performed with suitable personal protective equipment (PPE) for the hazards involved. The SPCC Coordinator may deny access, as needed, to maintain control of the situation and to prevent the spread of contamination outside of the Exclusion Zone. The number of access points to the Exclusion Zone shall be minimized.
- F. Control and Containment - During the emergency, the SPCC Coordinator will implement necessary actions to contain and control the situation and limit its spread. Containment will include the use of absorbent material, artificial and natural barriers to collect and contain oil, removing and isolating containers, and if necessary, the shutdown of processes and operations.
- G. Decontamination Procedures - Whenever access is made into the Exclusion Zone, appropriate decontamination personnel will be stationed inside the Contamination Reduction Zone. Such personnel shall be appropriately trained to provide decontamination services to personnel, equipment, or other materials exiting the Exclusion Zone.
- H. Decontamination shall occur at a level necessary to minimize the contamination of the response personnel, Support Zone, and outlying areas. Decontamination shall occur for all equipment, tools, waste containers, and personnel leaving the Exclusion Zone. The decontamination procedure and the materials needed are dependent on the nature of the contaminants and the level of PPE used by spill responders. Waste materials and discharge rinse water from decontamination shall be treated as contaminated waste and disposed appropriately.
- I. Disposal - Materials generated during an oil spill cleanup that require disposal could include oil, oil-contaminated speedy-dry, sorbent pads, sorbent booms, PPE, soil, water, etc. These materials must be managed, stored, and disposed of appropriately. Generally, in cases of a large release of oil, the oil spill cleanup contractor will provide transportation and disposal services.
- J. Actions Following an Emergency - The SPCC Coordinator shall be responsible for and will implement the following post-emergency activities:
- Where appropriate, all operational equipment will be checked to ensure integrity prior to restarting operations.
 - Hazardous materials, including contaminated soil and water, will be collected and stored for treatment and/or disposal. The SPCC Coordinator will ensure that no incompatible materials are stored together.
 - All emergency equipment will be cleaned and checked prior to the resumption of operations.
 - The VDEC and appropriate local authorities shall be notified that all hazardous material resulting from the emergency has been properly handled and that all emergency equipment is in order before resuming operations.

- The incident shall be recorded via a memorandum to file, recording the date, time, and details of the occurrence.

3.2.2 Facility Evacuation Plan

Due to the size and nature of operations at the Stowe Country Club Golf Course Maintenance Facility, it is unlikely that a large-scale evacuation would be necessitated by an oil spill. However, it is possible that localized evacuation may be needed to allow spill response personnel uninhibited access to contain and clean up a spill. Such localized evacuations can initially be implemented by Stowe Country Club Golf Course Maintenance Facility employees, at the direction of the SPCC Coordinator, and thereafter by Stowe Fire or Police Department personnel. If a building owned by the Stowe Country Club Golf Course Maintenance Facility requires evacuation, primary and alternate evacuation routes are depicted on plans posted strategically on walls throughout the buildings.

3.2.3 Duties and Responsibilities of the SPCC Coordinator

The SPCC Coordinator is responsible for coordinating all oil spill emergency response measures and has the authority to commit all resources required to implement the SPCC Plan. If the SPCC Coordinator is not available at the time of the oil release, the Alternate SPCC Coordinator shall undertake the duties of the SPCC Coordinator.

3.3 SPILL RESPONSE AND PERSONAL PROTECTIVE EQUIPMENT

Oil spill containment and cleanup kits are maintained at several locations throughout Stowe Country Club to enable Stowe Country Club Golf Course Maintenance Facility employees to affect a prompt response to incidental oil spills. Each kit contains the following types of equipment:

- Oil absorbent booms, pillows, and sheets;
- Loose sorbent;
- PPE (gloves, tyveks, over-boots, and safety glasses).

Note: The equipment listed above is intended to be used to contain and clean up small, incidental oil spills, and to enable employees to mount an incipient response to larger oil spills. At the discretion and direction of the SPCC Coordinator, larger spills will be handled by an outside contractor.

One large oil spill containment and cleanup kit capable of responding to a 65-gallon spill can be found in the barn equipment storage area close to the three 55-gallon drums.

Storm drains are not located proximate to oil tanks at the facility. If a release occurred from one of the exterior 500-gallon ASTs, oil would be conveyed across the parking lot to the entrance to the yard, into a vegetated ditch which leads to a storm drain within the Town of Stowe ROW. Because the Town ROW 12-inch corrugated metal culvert leads directly to the West Branch Little River, the application of storm drain mats or plugs during tank filling operations is considered necessary.

3.4 SPILL RESPONSE CONTRACTOR

Stowe Country Club maintains an active contract for emergency response to oil spills with the following contractor:

Environmental Products and Services	1.800.577.4557 802.862.1212 (Vermont)
-------------------------------------	------------------------------------------

3.5 SPILL REPORTING

Refer to the beginning of this document (pages i-ii) and Appendix D for emergency spill reporting procedures and contact phone numbers.

3.5.1 Federal Reporting

Title 40 of the CFR at Part 110, Discharge of Oil, requires that any person in charge of the facility, as soon as they have knowledge of a discharge that violates 40 CFR 110.6, Prohibited Discharge, must “immediately” notify the EPA NRC in Washington, D.C.

A prohibited discharge to the waters of the United States or its adjoining shoreline is defined to be a discharge in harmful quantities. Harmful quantities are defined at 40 CFR Part 110.3, to include discharges that:

- Violate water quality standards; or
- Cause a film or sheen upon or discoloration of the surface of the water or adjoining shorelines or cause a sludge or emulsion to be deposited beneath the surface of the water or upon the adjoining shoreline.

3.5.2 State Reporting

In addition to the federal reporting requirements, the Vermont Agency of Natural Resources requires all releases, including spills and overfills, that meet any of the following criteria shall be immediately reported to the Secretary by the owner of the tank:

- A release of heating fuel, motor fuel, or used oil that exceeds 2 gallons;
- A release of heating fuel, motor fuel, or used oil that is less than or equal to 2 gallons and poses a potential or actual threat to human health or the environment; or
- A release of heating fuel, motor fuel, or used oil that equals or exceeds its corresponding reportable quantity under CERCLA as specified under 40 CFR 302.4.

4. Inspections, Tests, and Records

4.1 GENERAL REQUIREMENTS

40 CFR 112.7(e) requires routine inspections, tests, and recordkeeping for oil storage tanks, piping, and equipment. Inspections and tests must be conducted in accordance with written procedures. Written procedures and a record of the inspections and tests must be kept and signed by the appropriate supervisor or inspector for a period of three years. Inspection forms are included in Appendix E. A photo log of the tank locations, photos provided by Stowe Country Club, is included as Appendix F.

4.2 SPECIFIC TESTING AND INSPECTION REQUIREMENTS

4.2.1 Tank Testing Requirements

40 CFR 112.8(c)(6) includes the following specific tank testing requirements:

- Each aboveground container must be tested for integrity on a regular schedule and whenever material repairs are made.
- The frequency and type of testing must take into account the container size and design.
- Testing must include visual inspection combined with another testing technique such as hydrostatic testing, radiographic testing, ultrasonic testing, acoustic emissions testing, or another system of non-destructive shell testing.
- Comparison records for visual and non-destructive tests must be kept on file.
- Each container's supports and foundations must be inspected on a regular basis.
- The outside of each container must be frequently inspected for signs of deterioration, discharges, or accumulation of oil inside secondary containment areas.

On a more frequent basis, if Stowe Country Club Golf Course Maintenance Facility employees observe stormwater in containment berms that requires draining, a written log documenting that no petroleum product (e.g., sheen or odor) was observed prior to pumping will be maintained for at least three years.

All other aboveground tanks and containers larger than 55-gallon capacity will be subject to routine visual inspections monthly and during filling plus another testing technique on a 10-year schedule. Fifty-five-gallon drums will be inspected monthly and removed from oil storage service when moderate corrosion or other damage to the container is noted that could result in a leak.

4.2.2 Transfer Piping Inspection Requirements

40 CFR 112.8(d)(4) includes the following specific inspection requirements:

- All aboveground valves, piping, and appurtenances must be regularly inspected.
- During the inspection, the general condition of items, such as flange joints, expansion joints, valve glands and bodies, catch pans, pipeline supports, locking of valves, and metal surfaces must be assessed.

- Integrity and leak testing of buried piping at the time of installation, modification, construction, relocation, or replacement must be conducted.

4.3 INSPECTION OF OIL STORAGE CONTAINERS, TANKS, AND PIPING

Inspections of aboveground containers, tanks, and piping will note any abnormal conditions such as:

- Evidence of leaky, worn, or deteriorating transfer lines;
- Evidence of leaky valves;
- Rust accumulation on tanks, valves, or lines;
- Unsafe conditions which could contribute to a spill of oil; and
- Deficiencies in spill kit inventory.

Completed inspection forms will be signed and dated by the inspector and kept on file for at least three years.

4.3.1 Monthly Inspections

The designated SPCC inspector will use an inspection form (Appendix E) to document monthly inspections of the following areas:

- Aboveground storage tanks and associated equipment (refer to section 1.4);
- Oil-filled electrical equipment (refer to section 1.4.26 for listing);
- Residential-type heating oil ASTs and associated piping (refer to section 2.1.2.3 for listing); and
- Spill Kits (see Appendix E for complete listing).

5. SPCC Training

Training for the purposes of this SPCC Plan is provided to all new employees with responsibilities for oil handling or storage or for oil spill response within one month of hire. Training is provided to current employees with those same responsibilities on an annual basis, or when changes in oil storage/handling are such that additional training is appropriate. The SPCC Plan Coordinator is responsible for assuring that the appropriate personnel complete the training requirements presented below.

The training program includes the following topics:

- Pollution control laws and regulations;
- Location, requirements, and contents of this SPCC Plan;
- Identification of the SPCC and Alternate SPCC Coordinators;
- Proper oil unloading and transfer procedures;
- Inspection and documentation responsibilities;
- Operation and maintenance of equipment to prevent discharges;
- Oil spill response techniques and notification procedures;
- Spill incident reporting and documentation;
- Security issues; and
- A review of any recent spill incidents, equipment malfunctions, procedural, or organizational revisions, or any other related changes to the oil pollution prevention program.

All training modules and training records will be maintained by the SPCC Coordinator for at least three years.

6. Security

During the winter and summer, Spruce Peak Loss Prevention personnel associated with Stowe Mountain Lodge are on call and conduct monitoring as a nightly drive-through security service at the maintenance facility. Security personnel conduct routine patrols to detect vandalism and other conditions adverse to the welfare of guests, employees, and the physical facility. Security personnel are cognizant of oil storage locations through their communications with the SPCC Coordinators.

Due to the nature of operations at Stowe Country Club Golf Course Maintenance Facility, fencing is an impractical means of securing aboveground oil storage locations throughout the property. However, the combination Spruce Peak Loss Prevention personnel monitoring, security devices on product pumps, and generally limited access to oil storage locations are considered appropriate to provide equivalent environmental protection.

7. Conformance to Applicable Federal SPCC Standards

Stowe Country Club Golf Course Maintenance Facility's operations conform to applicable oil spill prevention, control, and countermeasures requirements.

If changes are made at the facility that materially affect the oil storage capacity on site, or the potential for a discharge of oil, the SPCC Plan will be amended within six months of the change.


8. Plan Certifications

8.1 PROFESSIONAL ENGINEER CERTIFICATION

I have reviewed this Spill Prevention Control and Countermeasures (SPCC) Plan and the Plan satisfies the requirements of 40 CFR Part 112, Oil Pollution Prevention. Being familiar with the provisions of the Oil Pollution Prevention regulations, I attest that this SPCC Plan has been prepared in accordance with good engineering practices, including consideration of applicable industry standards and is adequate for the facility. Procedures for required inspections and testing have been established. This certification in no way relieves the owner or operator of this facility of his duty to prepare and fully implement this plan in accordance with the Oil Pollution Prevention regulations.

Jeffery A. Miller, P.E.

Printed Name of Licensed Professional Engineer




Signature of Licensed Professional Engineer

License No: 134753

State of: Vermont

Date: 16 June 2022



Seal

8.2 FACILITY CERTIFICATION

I certify that Stowe Country Club has the necessary personnel and equipment resources available to respond to a discharge within appropriate response times and/or have a written contractual agreement with an oil spill removal organization that identifies and ensures the availability of the necessary personnel and equipment within the appropriate response times. I hereby approve this SPCC Plan and authorize the commitment of the resources necessary to implement this plan.

Printed Name of Stowe Country Club Official

Title

Signature of Stowe Country Club Official

Date

9. Cross-Reference to SPCC Plan Regulations

Refer to Table III for SPCC rule cross-reference to this plan.

TABLES

TABLE I
SUMMARY OF OIL STORAGE AND USE
 SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN
 STOWE COUNTRY CLUB GOLF COURSE MAINTENANCE FACILITY
 STOWE, VERMONT

	Tank Name	Figure #	Drainage Area	Location	Type of Storage	ID	VT UST Registration No.	Capacity (gallons)	Tank Content	Used For	Tank Construction	Containment / Diversionary Structure	Notes
Aboveground Oil Tanks (ASTs)	Diesel AST	2	N/A	outside	AST	--	n/a	500	Diesel	Fueling Equipment	Double-Wall Steel	N/A	A current 350-gallon AST is to be replaced by a 500-gallon AST in the summer of 2022. The existing tank is single-walled steel with secondary containment to be replaced with a double-walled tank. No nearby drains.
	Gasoline AST	2	N/A	outside	AST	--	n/a	500	Gasoline	Fueling Equipment	Double-Wall Steel	N/A	A current 350-gallon AST is to be replaced by a 500-gallon AST in the summer of 2022. The existing tank is single-walled steel with secondary containment to be replaced with a double-walled tank. No nearby drains.
	Olsen House Heating Oil AST	2	N/A	inside	AST	--	n/a	275	#2 Fuel Oil	Building Heat	Single Wall Steel	Secondary Containment	No nearby drains
	Total AST Capacity								1,275				
Drums	Barn Equipment Storage Area Drums	2	N/A	inside	Drums (3)	--	n/a	110	Hydraulic Oil, Motor Oil, and Waste Oil	Waste	Single wall	Spill containment pallets	Of the 3 drums in the Equipment Storage Area, only 2 drums are typically filled with a third empty as backup storage. Therefore, the storage capacity is 110 gallons. No nearby drains.
	Shop Area Drums	2	N/A	inside	Drums (2)	--	n/a	110	Engine Oil and Hydraulic Oil	Equipment	Single wall	Spill containment pallets	No nearby drains
	Total Drum Capacity								220				
Oil Filled Operational Equipment	Shop Area Hydraulic Lift		N/A	inside	Oil-Filled Equipment	--	n/a	12 Quarts	Hydraulic Oil	Hydraulic Lifting	n/a	n/a	The hydraulic lift is contained within the Shop Area building. Any spills would be contained within the building as there are no nearby drains.
	Total Oil-Filled Operational Equipment Capacity								12 quarts				
Total Oil Storage On-Site								1,495					

TABLE II
PREDICTION OF POTENTIAL OIL RELEASES
 SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN
 STOWE COUNTRY CLUB GOLF COURSE MAINTENANCE FACILITY
 STOWE, VERMONT

Location	Drainage Area	Source	Type of Release	Opportunity for Discharge to Surface Water	Potential Release Amount (Maximum)
Exterior Diesel AST	Stowe Country Club	Diesel AST	Overfill during tank loading/unloading	If a release occurred from one of the exterior 500-gallon ASTs, oil would be conveyed across the parking lot to the entrance to the yard, into a vegetated ditch which leads to a 12-inch corrugated metal culvert within the Town of Stowe ROW. Because the Town ROW culvert leads directly to the West Branch Little River, the application of storm drain mats or plugs during tank filling operations is considered necessary.	500 gallons
			Truck/Equipment transfer line rupture		
Exterior Gasoline AST	Stowe Country Club	Gasoline AST	Overfill during tank loading		500 gallons
			Truck/Equipment transfer line rupture		
Olsen House Heating AST	Stowe Country Club	#2 Heating Oil AST	Overfill during tank loading	Release contained within basement area	275 gallons

SPCC RULE CROSS-REFERENCE

SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN
 STOWE COUNTRY CLUB GOLF COURSE MAINTENANCE FACILITY
 STOWE, VERMONT

SPCC Rule	Description of Section	Section(s) in Plan
§ 112.7	General requirements for SPCC Plans for all facilities and all oil types.	Section 8.2
§ 112.7(a)	General requirements; discussion of facility's conformance with rule requirements; deviations from Plan requirements; facility characteristics that must be described in the Plan; spill reporting information in the Plan; emergency procedures.	Section 7, Figures (all), Table I, section 2, Section 3, pages i-ii
§ 112.7(b)	Fault analysis.	Table II
§ 112.7(c)	Secondary containment.	Section 2.1.2
§ 112.7(d)	Contingency planning.	Section 3
§ 112.7(e)	Inspections, tests, and records.	Section 4
§ 112.7(f)	Employee training and discharge prevention procedures.	Section 5
§ 112.7(g)	Security (excluding oil production facilities).	Section 6
§ 112.7(h)	Loading/unloading (excluding offshore facilities).	N/A
§ 112.7(i)	Brittle fracture evaluation requirements.	N/A
§ 112.7(j)	Conformance with state requirements.	pages i-ii
§ 112.8(a) § 112.12(a)	General and specific requirements.	Sections cited above
§ 112.8(b) § 112.12(b)	Facility drainage.	Section 2.1.2.4
§ 112.8(c) § 112.12(c)	Bulk storage containers.	Section 2.1.2.4
§ 112.8(d) § 112.12(d)	Facility transfer operations, pumping, and facility process.	Section 2.2, Section 4.2.2
§ 112.9 § 112.13	Requirements for onshore production facilities.	N/A
§ 112.9(a) § 112.13(a)	General and specific requirements.	N/A
§ 112.9(b) § 112.13(b)	Oil production facility drainage.	N/A
§ 112.9(c) § 112.13(c)	Oil production facility bulk storage containers.	N/A
§ 112.9(d) § 112.13(d)	Facility transfer operations, oil production facility.	N/A
§ 112.10 § 112.14	Requirements for onshore oil drilling and workover facilities.	N/A
§ 112.10(a) § 112.14(a)	General and specific requirements.	N/A
§ 112.10(b) § 112.14(b)	Mobile facilities.	N/A
§ 112.10(c) § 112.14(c)	Secondary containment - catchment basins or diversion structures.	N/A
§ 112.10(d) § 112.14(d)	Blowout prevention (BOP).	N/A
§ 112.11 § 112.15	Requirements for offshore oil drilling, production, or workover facilities.	N/A

SPCC RULE CROSS-REFERENCE

SPILL PREVENTION CONTROL AND COUNTERMEASURES PLAN
 STOWE COUNTRY CLUB GOLF COURSE MAINTENANCE FACILITY
 STOWE, VERMONT

SPCC Rule	Description of Section	Section(s) in Plan
§ 112.11(a) § 112.15(a)	General and specific requirements.	N/A
§ 112.11(b) § 112.15(b)	Facility drainage.	N/A
§ 112.11(c) § 112.15(c)	Sump systems.	N/A
§ 112.11(d) § 112.15(d)	Discharge prevention systems for separators and treaters.	N/A
§ 112.11(e) § 112.15(e)	Atmospheric storage or surge containers; alarms.	N/A
§ 112.11(f) § 112.15(f)	Pressure containers; alarm systems.	N/A
§ 112.11(g) § 112.15(g)	Corrosion protection.	N/A
§ 112.11(h) § 112.15(h)	Pollution prevention system procedures.	N/A
§ 112.11(i) § 112.15(i)	Pollution prevention systems; testing and inspection.	N/A
§ 112.11(j) § 112.15(j)	Surface and subsurface well shut-in valves and devices.	N/A
§ 112.11(k) § 112.15(k)	Blowout prevention.	N/A
§ 112.11(l) § 112.15(l)	Manifolds.	N/A
§ 112.11(m) § 112.15(m)	Flowlines, pressure sensing devices.	N/A
§ 112.11(n) § 112.15(n)	Piping; corrosion protection.	N/A
§ 112.11(o) § 112.15(o)	Sub-marine piping; environmental stresses.	N/A
§ 112.11(p) § 112.15(p)	Inspections of sub-marine piping.	N/A

FIGURES



SITE COORDINATES: 44°28'41"N, 72°41'57"W



MAP SOURCE: USGS

**HALEY
ALDRICH**

SPILL PREVENTION CONTROL & COUNTERMEASURES PLAN
STOWE COUNTRY CLUB GOLF COURSE
MAINTENANCE FACILITY
STOWE, VERMONT

PROJECT LOCUS

APPROXIMATE SCALE: 1 INCH = 2,000 FEET
JULY 2022

FIGURE 1



APPROXIMATE LOCATION OF CURRENT:
TWO 350-GALLON ASTS -
GASOLINE AND DIESEL
PROPOSED:
TWO 500-GALLON ASTS -
GASOLINE AND DIESEL

APPROXIMATE LOCATION OF
TWO 55-GALLON
DRUMS - ENGINE OIL
AND HYDRAULIC OIL

APPROXIMATE LOCATION OF
THREE 55-GALLON
DRUMS - HYDRAULIC
OIL, MOTOR OIL, AND
WASTE OIL

SHOP AREA

BARN
EQUIPMENT
STORAGE

APPROXIMATE LOCATION OF
HYDRAULIC LIFT -
12 QUARTS OF
HYDRAULIC OIL

APPROXIMATE
LOCATION OF
275-GALLON HEATING
OIL TANK IN BASEMENT

TENT
EQUIPMENT
STORAGE

EQUIPMENT
WASH PAD

ABANDONED
RACKETBALL
COURT

OLSON HOUSE

PESTICIDE
STORAGE
BUILDING

CAPE COD ROAD

WEST BRANCH LITTLE RIVER


NOTE
1. IMAGE, DATED 19 SEPTEMBER 2021, TAKEN ELECTRONICALLY FROM GOOGLE EARTH PRO.

HALEY ALDRICH SPILL PREVENTION CONTROL & COUNTERMEASURES PLAN
STOWE COUNTRY CLUB GOLF COURSE
MAINTENANCE FACILITY
STOWE, VERMONT

**SITE PLAN -
STOWE COUNTRY CLUB GOLF
COURSE MAINTENANCE FACILITY**

SCALE: AS SHOWN
JULY 2022

FIGURE 2



Saved by: DTE
J:\GRAPHICS\131315\131315-005-B002.DWG
Printed: 4/27/2022 3:34 PM
Sheet: B002

APPENDIX A

SPCC Plan Review Log

LOG OF SPCC PLAN REVIEW AND REVISIONS

Date of Review	Reason for Review	Was Plan Revised?	PE Certification Required for Revision?	PE Certification Done?
4/26/2022	Stowe Country Club Golf Course Maintenance Facility increased its oil storage capacity so that it exceeds the limit that requires an SPCC plan of 1,320-gallons.	Yes	Yes	

"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on _____ (date), and will (will not) amend the Plan as a result."

Name _____ Date _____

Signature _____

"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on _____ (date), and will (will not) amend the Plan as a result."

Name _____ Date _____

Signature _____

"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on _____ (date), and will (will not) amend the Plan as a result."

Name _____ Date _____

Signature _____

"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on _____ (date), and will (will not) amend the Plan as a result."

Name _____ Date _____

Signature _____

"I have completed review and evaluation of the SPCC Plan for Stowe Country Club on _____ (date), and will (will not) amend the Plan as a result."

Name _____ Date _____

Signature _____

APPENDIX B

Example Sheen Inspection Log

**APPENDIX B EXAMPLE SHEEN INSPECTION LOG
FOR SECONDARY CONTAINMENT STRUCTURES**
(for use when water has accumulated in containment structure)

Date of Inspection: _____

Name of Inspector: _____

Signature of Inspector: _____

1. Description of Secondary Containment and Oil-Containing Unit (include location):

2. Type of Oil in Unit: _____

3. Oil Capacity of Unit: _____

4. Depth of water accumulated in Containment Cell (inches): _____

5. Remaining capacity in Containment Cell (inches): _____

	YES	NO	N/A
6. Is there an odor from the liquid accumulated in the cell?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Is there any visual evidence of leaks in the unit?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Is there a sheen on the liquid in the containment cell?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Is there anything unusual about the liquid in the cell?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

9. If yes, describe: _____

If a "yes" answer was recorded for any item above, the SPCC Coordinator must be notified, and corrective action must be taken prior to pumping liquid out of containment cell.

	YES	NO	Date:
10. Was the SPCC Coordinator notified?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="text"/>


11. Was the liquid pumped out of containment cell?	<input type="checkbox"/>	<input type="checkbox"/>	<input type="text"/>
----------------------------------------------------	--------------------------	--------------------------	----------------------

12. Where was the liquid discharged? _____

13. Approximate volume of liquid discharged? _____

13. Name of disposal company(if any) _____

Signature of SPCC Coordinator or Designee: _____



Construction Discharge Water Form

WO# _____
 Date _____
 Open WO _____

Project Project Description <input type="text"/>		Location _____ _____ _____		Estimated _____ Project Duration _____ Operator: _____		Supervisor: _____ Manager: _____	
Other: _____							

Site Description Grade <input type="text"/>		Vegetation @ site <input type="text"/>		Estimated Open Terrain _____		Excavation required Yes <input type="checkbox"/> No <input type="checkbox"/>	
-------------------------------------------------------	--	----------------------------------------	--	------------------------------	--	------------------------------------------------------------------------------	--

Water Course Water Infiltration Anticipated Yes <input type="checkbox"/> No <input type="checkbox"/>		Water Clarity - Pre Treatment <input type="text"/>		Nearest potentially impacted waterway _____ Feet			
Approx. Flow <input type="text"/>		Water Clarity - Post Treatment <input type="text"/>		Any drop-inlets, culverts or other paths for silty water to enter a waterway Yes <input type="checkbox"/> No <input type="checkbox"/>			
De-watering Method Used <input type="text"/>		De-siltation Method <input type="text"/>		Method used to prevent silty effluent from entering waterway <input type="text"/>			
Distance to nearest drainage _____ Feet							

Visual Waterway Inspection	Times	Ok	Ok	Ok	Ok	Ok	Ok	Ok	Ok	
Check periodically through out project to ensure there is no silt infiltration into the waterway	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>
Increase frequency of checks with turbidity level	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>	_____	<input type="checkbox"/>

<input type="checkbox"/> Cat 1 Project involves work within the confines of a water way. VT 1272 Permit required. Director Level Authority Only	<input type="checkbox"/> Cat 3 Drainage entry point is 100' from site Water-infiltration is below 25gal / min
<input type="checkbox"/> Cat 2 Drainage entry point is within 50' of site. Water-infiltration is above 25gal / min. Extreme turbidity of pretreated water. Director Level Authority Only	<input type="checkbox"/> Cat 4 Drainage entry point is 500' from site Little water-infiltration

Site Closure Date Completed _____		Site Clean-up description: _____ _____ _____		Was site mulched Yes <input type="checkbox"/> No <input type="checkbox"/> N/A <input type="checkbox"/>		
Time _____				Does site require Silt Fence <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		
Inspected by: _____				Has site been posted for travel <input type="checkbox"/> <input type="checkbox"/> <input type="checkbox"/>		

Accountability " I attest that I have managed the site with reference to water quality to the best of my ability. I have not willing or with any knowledge contributed to the degradation of the surrounding waterway		Approved by: _____ Director Level _____ Manager Level	
_____ Initiating Supervisor			

APPENDIX C

Fueling Procedures

Stowe Country Club Golf Course
Maintenance Facility

Bulk Fueling Procedures for Oil Storage Tanks

Bulk Fueling Procedures for Heating Oil, Gasoline, and Diesel Fuel Tanks:

Additional Precautions for the following tanks: Exterior Gasoline and Diesel Fuel Tanks (500-gallons each) and Olsen House Heating Oil AST (275-gallon)

DOCUMENT OWNERS: Director of Agronomy (Kevin Komer)

PURPOSE: To ensure the safe and secure bulk transfer of fuel to Stowe Country Club fuel storage tanks

DATE OF ISSUANCE: April 25, 2022

DATE OF REVISION:

Personnel - The procedure requires a minimum of two people, typically one authorized Stowe Country Club employee and the fuel vendor company employee.

Fuel Vendor - Fuel truck deliveries will not be permitted at the locations identified above without prior communication.

1. Prior to delivery fuel vendor will contact the Primary SPCC Coordinator, Kevin Komer, for heating oil deliveries or Lift Maintenance for diesel fuel deliveries. Telephone number: **(802) 253-3458**;
2. Stowe Country Club (equipment technician) ensures the fill location is accessible to the fuel truck.

Training

1. All authorized Stowe Country Club employees will receive training in the following areas:
 - a. Spill Response (annual)
 - b. Review of Oil Spill Contingency Plans as needed; and
 - c. Review of relevant fueling procedures (annual).
2. Training of fuel delivery company personnel will be conducted whenever a delivery company employee who is not familiar with Stowe Country Club's operations arrives on site.
3. It is the responsibility of Stowe Country Club Managers to conduct and document vendor training and transmit the documentation to the Environmental Management Representative for retention.

Tank Size – Maximum allowable fuel delivery volume

1. Authorized Stowe Country Club employees determines fuel volume with AST 90-percent full (**Tanks should be filled to a maximum of 90-percent full to allow for expansion.**).
2. An authorized Stowe Country Club employee determines the current volume of fuel in AST.
3. An authorized Stowe Country Club employee calculates the maximum allowable delivery volume (i.e., 90 percent volume minus current volume).

Pre-Fueling

1. An authorized Stowe Country Club employee opens the fuel port and determines the current fuel volume in the tank as well as the maximum allowable fill volume.
2. If fueling is taking place at a location where Site Specific Precautionary Measures are required to address site specific concerns (see below) Stowe Country Club ensures the designated measures are in place.
3. Delivery person hooks up fuel hoses.

Pre-Fueling (Cont.)

4. An authorized Stowe Country Club employee conducts visual inspection of the following:
 - a. Drip bucket present and empty, if applicable.
 - b. Transfer port and tank coupling are secure.

Fuel delivery person begins transferring fuel to the fuel tank.

During Fueling

1. An authorized Stowe Country Club employee will periodically conduct a visual inspection of the following during transfer;
 - a. Delivery vehicle;
 - b. Fuel deliver route (hoses and pipes); and
 - c. Fuel ports.
2. ASTs should be filled to a maximum of 90% full to allow adequate space for expansion.

Post Fuel

1. The fuel delivery person closes transfer valves and disconnects the hoses.
2. An authorized Stowe Country Club employee secures port cap
3. The authorized Stowe Country Club employee and delivery truck driver conduct visual inspection of the following;
 - a. Drip bucket empty, if applicable;
 - b. Drain seal has been removed, if applicable;
 - c. Fuel port closed and secured
 - d. No visible signs of product along the transfer line.
 - e. Transport carrier is secured and ready for transport
4. The authorized Stowe Country Club employee checks the spill supplies and if depleted obtains additional supplies.

Site Specific Precautionary Measures

Fueling locations identified below require additional precautionary measures to address site specific conditions and comply with Stowe Country Club's Spill Prevention Control and Countermeasure (SPCC) Plan.

I) Exterior 500 -gallon Gasoline and Diesel Oil ASTs:

Bulk oil deliveries occur at the exterior gasoline and diesel fuel ASTs located in the northwest corner of the property once per week. Trucks deliver fuel to these ASTs which are located on a paved surface and within secondary containment. Storm drains are not located proximate to oil tanks within the property boundary. If a release occurred from one of the exterior 500-gallon ASTs, oil could be conveyed across the parking lot to the entrance to the yard, into a vegetated ditch which leads to a storm drain within the Town of Stowe Right-of-Way (ROW). Because the Town ROW storm drain leads directly to the West Branch Little River, a storm drain safety seal cover, mat or plug should be applied during fuel loading to prevent potential spills from reaching the storm drain system that leads to surface water.

II) Interior Olsen House Heating Oil Tank: Bulk fuel loading occurs for the interior Olsen House heating oil tank through an outside fill port approximately once per month.

A release during filling of the Olsen House heating oil tank would likely be contained within the basement area which does not have a floor drain.

APPENDIX D

Employee Spill Response Procedure

PURPOSE: To ensure an appropriate employee response in the event of a release of hazardous materials or oil.

DATE OF ISSUANCE: April 25, 2022

DATE OF REVISION:

If a Spill Occurs

Initial Assessment:

Assess the Risk: Determine the nature and quantity of the spill.

Notification to outside Agencies:

- a. If greater than 2 gallons of hazardous material or oil is released to soil or water, or
- b. if the spill appears to pose a threat to human health or the environment

Immediately contact a Spill Coordinator, after business hours contact a Night Coordinator.

Talk directly to the Coordinator; do not rely on a message.

The coordinator will determine the need to contact other parties/agencies.

<u>DAY COORDINATORS</u>			<u>NIGHT COORDINATORS (N/A)</u>	
	Office	Cell	Name	Number
Kevin Komer	802-253-3458	802-793-9108		
Andrew Chuber		913-683-8831		

Note: The Document Owner is responsible for identifying Day and Night Coordinators and providing contact information and keeping the information current. Updated versions should be provided to the Environmental Management Representative for posting on the EMS shared drive.

Notification Requirements

Release > 2.0 gallons

VTDEC requires immediate state notification of all releases to soil or water that are greater than or equal to 2.0 gallons or pose a threat to human health or the environment. This communication is handled by environmental or management personnel. A spill coordinator will contact the VT DEC directly as follows: **802-828-1138 (during business hours) 800-641-5005 (all other times)**

Release to a Surface Water Body (i.e., a sheen or more)

Federal law requires immediate National Response Center notification. This is handled by environmental or management personnel. The Spill Coordinators must contact the National Response Center directly as follows: **800-424-8802.**

-OVER-



Spill Response Procedure

NO. PAGE 2 OF 2

Notification Requirements (Continued)

The following information should be provided when reporting a release to VTDEC or the National Response Center:

- Location of the release
- Source of release
- Type of product released
- Estimated volume of release
- Time of release (if known)
- Affected media (soil, surface water)
- Response actions taken

For releases >1,000 gallons or two discharges of 42 gallons or more within 12 months

EPA Region 1 must be notified within 60 days of the release.

Response Action:

If spill conditions, training and available equipment permit, follow the sequence below:

1. **Select appropriate Personal Protective Equipment (PPE)**: If available PPE does not offer adequate protection, do not perform clean up activities.
2. **Stop Product Flow**: Act quickly to stop the source of spilled material, if possible. This minimizes the spill.
3. **Contain the Spill**: Use socks, dikes, or booms to contain the spill and keep it from spreading or contaminating water sources
4. **Absorb Contained Fluids**: Place absorbent pads and pillows directly on the spill to absorb material.
5. **Dispose and Decontaminate**: Remove contaminated material in compliance with local, state, and federal regulations. Decontaminate the site, personnel, and all equipment.

In the event that the release cannot be adequately contained, Stow Country Club personnel must immediately contact Environmental Products and Services 800-9SPILL9, Stow Country Club's designated 24/7 hazardous waste emergency responder.

Documentation:

Complete all required paperwork and reporting

ADDITIONAL EMERGENCY CONTACT PHONE NUMBERS:

Stowe Fire and Police Departments	911
Environmental Products and Services (cleanup contractor)	800-9SPILL9

APPENDIX E

Example SPCC Inspection Forms



Monthly Aboveground Storage Tank and Spill Kit Inspection Checklist

Date: _____

OK NG NA **ASTs**

- Tank Surfaces checked for signs of leakage
- Tank Condition (no rusting, corrosion, pitting)
- Tank Foundation intact
- Level gauges and alarms functioning properly
- Vents are not obstructed

OK NG NA **Piping**

- No leaks at valves, flanges or fittings
- No signs of corrosion damage to pipelines or supports
- Buried Pipelines not exposed
- Signs and barriers in place
- Fill port capped and locked

OK NG NA **Containment**

- Containment walls, floor intact
- No visible oil sheen in containment area
- No standing water in containment area
- Containment area valves closed

OK NG NA **Drainage**

- No oil sheens on runoff
- No soil staining or stressed vegetation

Inspection Location

- Sensation Lift 400-gallon and spill kit
- SCC Cart Barn 300-gal gasoline and spill kit
- SCC Maintenance Barn 300-gal diesel
- SCC Maintenance Barn 300-gal gasoline
- Gondola Base 130-gal diesel and spill kit.
- Gondola Booster Station 185-gal diesel and spill kit.
- Lookout Lift Summit 100-gal diesel and spill kit.
- Mobil fuel truck 100-gal diesel and spill kit.
- Sunny Spruce 170-gal diesel and spill kit
- Adventure Triple Lift 70-gal diesel and spill kit
- Quad Top 60gal & 400gal AST and spill kit

- Transfer Lift 155gal and Spill Kit
- SML I North Gen Set 600-gallon and spill kit
- SML II South Gen Set 275-gallon and spill kit
- Admin Building Emergency Generator 175-gallon diesel
- SCAMP Emergency Generator 1,500-gallon and spill kit
- Cliff House Tension System 77-gallon hydraulic & spill kit
- Diesel Pad 1K-gallon diesel day tank and spill kit
- Fueling Station 6k-gallon unleaded
- Fueling Station 15k-gallon diesel

OK NG NA **Spill Kit and Supplies**

- Sorbent pads and booms in stock
- PPE; gloves, Tyvek, safety-glasses

Key

- OK** Satisfactory
- NG** Repair or adjustment required
- NA** Not Applicable

Remarks / Recommendations

_____ Print Name

_____ Signature




Fuel Tank Inspection Report

- 15K Diesel - Snowmaking
- 1K Diesel - Snowmaking
- 6K Gasoline

Week Ending: _____

Station	Condition		NA	Remarks (Use reverse side for further descriptions)
	Satisfactory	Unsatisfactory		
Tank				
Quadrant #1	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Quadrant #2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Quadrant #3	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Quadrant #4	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Ground Straps	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Interstitial Space	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Tank Supports	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Tank Foundation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Pipelines				
Piping	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Valves	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Flanges	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Fill Port	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Dispensing				
Pump #1	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Pump #2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Nozzle #1	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Nozzle #2	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Hoses	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Physical				
Moorman Gauge	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Clock Gauge	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____
Alarms	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	_____

- Check appropriate box to indicate condition of each station. Describe location of any unsatisfactory conditions (use back of form if more space is needed)
- Satisfactory Evaluation: No visible signs of corrosion, wear, damage or leakage
- Unsatisfactory evaluation: Describe nature and location of deficiency.
- Immediately report to Department Supervisor any product leakage, spillage or facility conditions that could result in a fuel spill or pose immediate risk to health and safety.



Gauge Reading _____

Quantity _____

Product _____

Print Name _____

Signature _____



Monthly Residential-Type Heating Oil Aboveground Storage Tank Inspection Checklist

Date _____

OK NG NA **ASTs**

- Tank Surfaces checked for signs of leakage
 Tank Condition (no rusting, corrosion, pitting)
 Tank Foundation intact
 Level gauges and alarms functioning properly
 Vents are not obstructed

Inspection Location

- PC Construction Field Office; 275-gallon AST located in basement
 Property Operations Facilities Building; 275-gallon AST located outside along southeast wall.
 Olsen house @ SCC ; 275 gallon AST
Located in Basement

OK NG NA **Piping**

- No leaks at valves, flanges or fittings
 No signs of corrosion damage to pipelines or supports
 Buried Pipelines not exposed
 Signs and barriers in place
 Fill port capped and locked

OK NG NA **Containment**

- Containment walls, floor intact
 No visible oil sheen in containment area
 No standing water in containment area
 Containment area valves closed

OK NG NA **Drainage**

- No oil sheens on runoff
 No soil staining or stressed vegetation

Key

OK Satisfactory NG Repair or adjustment required
NA Not Applicable

Remarks / Recommendations

Print Name Signature



Stowe Mountain Club - Natural Resources Management Center Aboveground Storage Tank and Spill Kit Inspection Checklist

Date:

OK NG NA **ASTs**

- Tank Surfaces checked for signs of leakage
- Tank Condition (no rusting, corrosion, pitting)
- Tank Foundation intact
- Level gauges and alarms functioning properly
- Vents are not obstructed

Inspection Location

- 1,000-gallon diesel fuel AST
- 500-gallon gasoline AST
- 300-gallon waste oil AST

OK NG NA **Piping**

- No leaks at valves, flanges or fittings
- No signs of corrosion damage to pipelines or supports
- Buried Pipelines not exposed
- Signs and barriers in place
- Fill port capped and locked

OK NG NA **Containment**

- Containment walls, floor intact
- No visible oil sheen in containment area
- No standing water in containment area
- Containment area valves closed

OK NG NA **Spill Kit and Supplies**

- Sorbent pads and booms in stock
- PPE; gloves, Tyvek, safety-glasses

OK NG NA **Drainage**

- No oil sheens on runoff
- No soil staining or stressed vegetation

Key

OK Satisfactory

NG Repair or adjustment required

NA Not Applicable

Remarks / Recommendations

Print Name

Signature



Spill Kit Inspection Report and Checklist

Date:

Spill Kit and Supplies

OK NG

Facilities:

- Cliff House 4,000gal UST heating boiler room and generator room
- PC Construction Office 275gal AST
- Mansfield Base Lodge 2,000gal UST
- Quad Top
- Inn at the Mountain 12,000gal UST & 275gal AST
- Service Vehicles (x4)
- Spruce Camp Loading dock
- Octagon 10,000gal UST

Spill Kits:

- PPE
- Absorbents
- Response Sheet

Lifts:

- Lookout Lift top 500gal UST & 100gal AST
- Sensation Lift 2,000gal UST 400gal AST
- Adventure Triple 70gal day tank
- Gondola Base 1,000gal UST & 130gal AST
- Quad Top 400gal & 60gal AST
- Sunny Spruce 170gal AST
- Transfer Lift 130gal day tank
- Transfer Lift Spruce Side (small 5gal kit)

Snowmaking:

- Mobil Fuel Truck 100gal tank
- New Control
- Primary Pump House
- Gondola Booster 185gal AST backup generator
- Spruce Booster 700gal & 900gal transformers
- Diesel Pad 1,000gal AST

Golf Courses:

- SMC NRMC
- Stowe C. C. Cart Barn 300gal gasoline
- Stowe C.C. Maintenance Barn 300gal gasoline & 300gal diesel

Vehicle Maintenance:

- Vehicles
- Hazardous Waste Trailer
- Lift Maintenance

Stowe Mountain Lodge

- SML North
- SML South

Key

OK Satisfactory

NG Repair or adjustment required

Remarks / Recommendations

Print Name

Signature



Monthly Oil Filled Electrical Equipment Inspection

Date: _____

OK NG NA

Cliff House Restaurant; pad-mounted 450-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Gondola Base; pad-mounted 570-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Gondola Booster Station; pad-mounted 360-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Lookout Lift Summit; pad-mounted 315-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Performing Arts Center; pad-mounted 102-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Midway Lodge; pad-mounted 595-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Diesel Pad; pad-mounted 470-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:



Monthly Oil Filled Electrical Equipment Inspection

Date: _____

Snowmaking Control; pad mounted 400 gallon and 775-gallon mineral oil transformers

OK NG NA

394-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

775-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Over EasyTransfer Lift; pad-mounted 750-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

Primary Pump House; pad-mounted 610-gallon and 694-gallon mineral oil transformers

OK NG NA

694-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

610-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

Sunny Spruce Lift Base; pad-mounted 150, 417, and 840-gallon mineral oil transformers

OK NG NA

150-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

840-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

417-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Norms VH on Liftline; pad-mounted 700-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

Spruce Booster Station; pad-mounted 700 and 900-gallon mineral oil transformers

OK NG NA

700-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

900-gallon AST

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition; (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:



Monthly Oil Filled Electrical Equipment Inspection

Date: _____

OK NG NA

Spruce Camp @ Loading dock; pad-mounted 306-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

SML South; pad-mounted 285-gallon mineral oil transformers

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

SML North; pad-mounted 375 and 165-gallon mineral oil transformers

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition; (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

OK NG NA

165-gallon AST

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition; (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

SML Plaza; pad-mounted 190-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

SMC Cottage; pad-mounted 92-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Summit Building; 950-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Quad Lift Base; pad-mounted 100-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA

Sensation Lift Base; pad-mounted 700-gallon mineral oil transformer

- Tank condition (rusting, corrosion, pitting)
 Concrete pad condition (cracking or pitting)
 No evidence of a recent release (e.g, oil staining, stressed vegetation)



Monthly Oil Filled Electrical Equipment Inspection

Date: _____

Comments:

OK NG NA **Spruce Temporary Adventure Center Project; pad-mounted 200-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA **SMC NRM; pad-mounted 168-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA **Octagon Quad Summit; pad-mounted 563-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA **Meadows Quad Top; pad-mounted 240-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA **Easy St Trail Top; pad-mounted 240-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

OK NG NA **Lifeline Booster; pad-mounted 700-gallon mineral oil transformer**

- Tank condition (rusting, corrosion, pitting)
- Concrete pad condition (cracking or pitting)
- No evidence of a recent release (e.g, oil staining, stressed vegetation)

Comments:

Stowe Mountain Resort – Quarterly Hazardous Waste Storage Area Inspection Checklist

VARIABLE	REQUIREMENT / MAXIMUM ALLOWABLE			INSPECTION RESULT
	SQG	CEG	SMR	
Vermont Hazardous Waste Handler Site ID Number	VTD988366480			
WASTE STORAGE				
Quantity of hazardous waste stored on site (does not include universal waste or waste oil that is recycled)	13,200 lbs	2,200 lbs	2,200 lbs	Note: Three full soil drums ~ 2,200 lbs.
Length of time hazardous waste is on site	180 days	No limit	No limit	
Length of time universal waste is on site	1 year	1 year	1 year	
All waste stored under cover	Yes	Yes	Yes	
All waste stored on impervious surface	Yes	Yes	Yes	
All waste stored in closed containers	Yes	Yes	Yes	
All containers in good condition	Yes	Yes	Yes	
Wastes protected from freezing	Yes	Yes	Yes	
Aisle space of 24 inches or more	Yes	No	No	
“ Hazardous Waste Storage Area ” signs posted	Yes	No	Yes	
“ No Smoking ” signs posted	Yes, if ignitables are present	No	Yes	
Hazardous waste storage area inspections and logs completed	Daily	No	Weekly	
WASTE LABELING				
“Hazardous Waste” on containers	Yes	No	Yes	
Words “Federal Law Prohibits Improper Disposal” present on hazardous waste	Yes	No	Yes	
Generator’s name, address and EPA ID number present on container	Yes	No	Yes	

Stowe Mountain Resort – Quarterly Hazardous Waste Storage Area Inspection Checklist

VARIABLE	REQUIREMENT / MAXIMUM ALLOWABLE			INSPECTION RESULT
	SQG	CEG	SMR	
Waste name and hazardous waste ID number present on container	Yes	No	Yes	
Date waste placed into storage present	Yes	No	Yes	
WASTE DISPOSAL				
Hazardous Waste Manifest utilized	Yes	No	Yes	
Certified transporter utilized	Yes	No	Yes	
Compliance with Federal Land Disposal Restrictions	Yes	No	Yes	
EMERGENCY RESPONSE				
Employee Spill Response Procedure posted in storage area	Yes	No	Yes	
Employee Spill Response Procedure posted near phone in Vehicle Maintenance	Yes	No	Yes	
Annual hazardous waste training	Yes	No	No	
Emergency communication device at storage area	Yes	No	No	
Fire and spill control equipment present in storage area	Yes	No	Yes	

Notes:

SQG – Indicates Small Quantity Hazardous Waste Generator:

CEG – Indicates Conditionally Exempt Hazardous Waste Generator:

SMR – Indicates Stowe Mountain Resort: and

Inspections are to be performed quarterly by the Environmental Coordinator and documented through completion of a Quarterly Inspection Checklist.

APPENDIX F

Photo Log

Stowe Country Club Golf Course Maintenance Facility
Stowe, Vermont
File No. 0131315-005
Date Photographs Taken: April 2022 – Photos taken and provided by Client



Photo 1: Stowe Country Club Maintenance Facility facing southwest toward equipment storage barn



Photo 2: Two 350-gallon gasoline and diesel fuel ASTs



Photo 3: Stowe Country Club Maintenance Facility facing southeast toward Olsen House



Photo 4: Two 55-gallon drums stored on portable spill containment pallets in the Shop Area




Photo 5: Shop area hydraulic lift and drums



Photo 6: Barn equipment storage area vehicles, drums, and 5-gallon buckets

Stowe Country Club Golf Course Maintenance Facility
Stowe, Vermont
File No. 0131315-005
Date Photographs Taken: April 2022 – Photos taken and provided by Client



Photo 7: Two 350-gallon gasoline and diesel fuel ASTs from a distance facing north



Photo 8: Two 350-gallon gasoline and diesel fuel ASTs



Photo 9: Olsen House exterior



Photo 10: 275-gallon heating oil AST within secondary containment in Olsen House basement




Photo 11: 275-gallon heating oil AST Sticker



Photo 12: Pesticide Storage Building

Stowe Country Club Golf Course Maintenance Facility
Stowe, Vermont
File No. 0131315-005
Date Photographs Taken: April 2022 – Photos taken and provided by Client



Photo 13: Equipment Wash Area



Photo 14: Barn equipment storage area drums



Photo 15: Inside of secondary containment for two 350-gallon gasoline and diesel fuel ASTs



Photo 16: Inside of secondary containment for two 350-gallon gasoline and diesel fuel ASTs



Photo 11: 350-gallon AST secondary containment



Photo 12: 275-gallon AST secondary containment

Stowe Country Club Golf Course Maintenance Facility

Stowe, Vermont

File No. 0131315-005

Date Photographs Taken: April 2022 – Photos taken and provided by Client



Photo 13: 12 inch Corrugated Metal Culvert leading to the West Branch Little River



Photo 14: 65-gallon spill kit within the barn equipment storage area

CARBTR0L

ADVANCED WASHWATER RECYCLE SYSTEMS

(MODELS GCW-3 GCW-4)



Engineered systems provide:

- * Best Available Technology*
- * Closed Loop Recycling*
- * High Reliability and Low Maintenance*

Typical Applications:

- * Golf Course Maintenance*
- * Vehicle Washing*
- * Equipment Cleaning*



Carbtrol Corporation

200 Benton St

Stratford, CT 06607

800.242.1150 - www.carbtrol.com

Attachment E - Carbtrol Brochure

CARBTROL

ADVANCED WASHWATER RECYCLE SYSTEM



PRIMARY COLLECTION SUMP

Dirty wash water collects in the primary sump. At water high level, the pump engages. During pumping, the water is vigorously agitated to ensure that grass, and dirt, do not accumulate in the sump.



HYDRO SCREEN AND GRASS CART

Dirty water is pumped from primary sump to the solids separation screen. Grass and dirt are filtered by the screen and collected in a grass cart. Filtered water passes through the screen and flows into a transfer sump.



CLARIFIER & WATER STORAGE

Screened wash water is pumped from transfer sump to the clarifier where additional solids are removed by quiescent settling. The clarified water then flows to a storage tank, prior to final treatment and reuse.



TREATMENT AND RECYCLE PACKAGE

Clarified washwater is pumped to the treatment system which includes sand filtration and activated carbon adsorption. Oxidation using ozone and hydrogen peroxide provides final polishing. Water is available on demand.